CORRECTER xi abmit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Revised March 25, 1999 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-041-00139 District II OIL CONSERVATION DIVISION 811 South First, Artesia, NM 88210 5. Indicate Type of Lease 2040 South Pacheco District III STATE \square FEE X 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A MILNESAND UNIT DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Gas Well Other INJECTION Oil Well \square 8. Well No. 196 2. Name of Operator J. CLEO THOMPSON 9. Pool name or Wildcat Address of Operator MILNESAND (SAN ANDRES) 325 N. ST. PAUL. SUITE 4300, DALLAS, TX 75201 Well Location Unit Letter N : 660 feet from the SOUTH line and 1980 feet from the WEST line Township 8S Range 34E County ROOSEVELT Section 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4262' RKB 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK ALTERING CASING PLUG AND COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS **ABANDONMENT** CASING TEST AND PULL OR ALTER CASING MULTIPLE **CEMENT JOB** COMPLETION OTHER OTHER: REPAIR INJECTION WELL 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1.) RIH W/2 3/8 TUBING AND TAG PLUG AT 4415". 2.) CIRCULATE 9.5# SALT MUD TO SURFACE. 3.) PULL UP TO 2280' AND CIRCULATE 56 SX OF CLASS "C" NEAT CEMENT. 4.) PULL UP TO 2000' AND REVERSE CIRCULATE WITH 9.5# SALT MUD. 5.) PULL TUBING to 489 6.) CIRCULATE 25 SX CLASS "C" CEMENT.AT 489" 7.) PULL UP TO 250' AND REVERSE CLEAN. POOH. WAIT I HOUR AND RIH AND TAG CEMENT PLUG. POOH. SET 10 SX SURFACE PLUG. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE ENGINEER DATE JUNE 22, 2001 **SIGNATURE**

TITLE

THE COMPRESSOR MINE SE MOTHED 2.4 HOURS PRIOR TO THE SECTIONING OF RUGGING OPERATIONS FOR THE CHAST TO BE APPROVED.

Telephone No. (915)366-8886

Type or print name

APPPROVED BY

(This space for State use)

Conditions of approval, if any:

JIM STEVENS

TO A STANSON BY