



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **New Mexico**

Lease No. **033910**

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal-McGrail Lease

September 18, 1958

Well No. **1** is located **1980** ft. from **[N]** line and **1980** ft. from **[E]** line of sec. **20**

SE NW Sec. 20

8S

37E

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Wildcat

Roosevelt

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing programs, and all other important proposed work.)
Plan to drill a Devonian test well to a depth of 11,500'. Following is casing

13-3/8", 48#, set at 350' with 350 sacks cement, circulated.

9-5/8", 36#, set at 4200' with 1900 sacks cement, circulated.

7", 23#, 26#, 29# & 32#, set at 11,500' with 1800 sacks cement, sufficient to protect all known oil and water formations.

All casing will be cemented and tested by approved method.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **THE OHIO OIL COMPANY**

Address **Box 2107**

Robbs, New Mexico

By **D. E. Morris**

Title **Assistant Supt.**

DISTRIBUTION: U.S. S.

Mr. J. A. Grimes

Mr. L. H. Shearer

Mr. D. V. Kitley

Mr. T. A. Steele

Mr. T. O. Webb

Mr. C. M. Lynch