

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI-CATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		JUL 13 1981	
2. NAME OF OPERATOR JFG ENTERPRISES		O. C. D.	
3. ADDRESS OF OPERATOR P.O. Box 100, Artesia, N.M. 88210		ARTESIA, OFFICE	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 FST & 1980 FEL Sec. 20-T8S-R37E		5. LEASE DESIGNATION AND SERIAL NO. NM-28056	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR-4033 Ft.	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
NOTICE OF INTENTION TO:		7. UNIT AGREEMENT NAME	
TEST WATER SHUT-OFF <input type="checkbox"/>		8. FARM OR LEASE NAME Silver A Fed.	
PULL OR ALTER CASING <input type="checkbox"/>		9. WELL NO. 1	
FRACTURE TREAT <input type="checkbox"/>		10. FIELD AND POOL, OR WILDCAT Allison-Penn	
MULTIPLE COMPLETE <input type="checkbox"/>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20-T8S-R37E	
ABANDON* <input checked="" type="checkbox"/>		12. COUNTY OR PARISH Roosevelt	
CHANGE PLANS <input type="checkbox"/>		13. STATE New Mexico	
(Other) <input type="checkbox"/>			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-10-81: Dug out cellar and welded up wellhead.

4-11-81: Move in Reverse Rig.

4-13-81: Started Drlg. out.

4-14-81: Continue to drill out plugs.

4-15-81: Drill out to 4251 ft. & reached inside of 7".

4-22-81: Reached 5767 ft. - unable to drill deeper.
Called Pete Chester and received permission to plug & abandon.
Plan to Plug & Abandon.
Plan to set 40 sx. Plug at 5767 ft. & 40 sx. Plug 4170 ft. to 4220 ft. & 10 sx. Plug at surface.

RECEIVED
JUL 9 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED R. J. Zlotche TITLE Agent DATE 7-8-81

(This space for Federal Approval)
(Orig. Sgd.) ROGER A. CHAPMAN

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUL 9 1981

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

TRANSFER
11/17/81

RECEIVED
OCT 17 1981
OIL CONSERVATION DIV.

RECEIVED
OCT 17 1981
OIL CONSERVATION DIV.