	L' TED STATES PARTMENT OF THE INTE		ATE• Form approved. Budget Bureau No. 42- 5. LEASE DESIGNATION AND SERIAL	
		-	NM 045651 B	
	NOTICES AND REPORTS	s on wells	6. IF INDIAN, ALLOTTEE OR TRIBL	
(Do not use this form f Use	A proposals to drill onto drenen or pl	ug back to a different reservoir. ch proposals.)	- <b></b>	
			7. UNIT AGREEMENT NAME	
WELL WELL C	OTHER		8. FARM OR LEASE NAME	
Mar	Silver "D" Federal			
3. ADDRESS OF OPERATOR	9. WELL NO.			
	O. Box 220, Hobbs, New ocation clearly and in accordance with		10. FIELD AND POOL, OF WILDCAT	
See also space 17 below.) At surface	Allison-Penn			
	660' FSL and 1980' FWL			
			Sec. 21-85-37E	
14. PERMIT NO.	15. ELEVATIONS (Show whethe		12. COUNTY OB PARISH 13. STATE	
<u></u>		4061'	Roosevelt New M	
16. Ch	eck Appropriate Box To Indicate	e Nature of Notice, Report,	or Other Data	
NOTICE	OF INTENTION TO:	80	BSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZIN	ALTERING CASING ABANDONMENT* X	
REPAIR WELL	CHANGE PLANS	(Other)		
(Other)		(NOTE : Report r Completion or Re	esults of multiple completion on Weil completion Report and Log form.)	
off at 5090'. Placed Placed 40 sack cement cement plug in the 9-5 steel marker was insta	nt plug at TD 9509' to o a 20 sack cement plug f plug across the 9-5/8" 5/8" casing at the surfa alled per NMOCC specific	in and out of 5-1/2" casing shoe at 4205 ace. The hole was f	cut off casing. '. Placed a 10 sack illed with mud. A	
off at 5090'. Placed Placed 40 sack cement cement plug in the 9-5	a 20 sack cement plug f plug across the 9-5/8" 5/8" casing at the surfa	in and out of 5-1/2" casing shoe at 4205 ace. The hole was f	cut off casing. '. Placed a 10 sack illed with mud. A	
off at 5090'. Placed Placed 40 sack cement cement plug in the 9-5 steel marker was insta	a 20 sack cement plug i plug across the 9-5/8" 5/8" casing at the surfa alled per NMOCC specific	in and out of 5-1/2" casing shoe at 4205 ace. The hole was f	cut off casing. '. Placed a 10 sack illed with mud. A	
off at 5090'. Placed Placed 40 sack cement cement plug in the 9-5 steel marker was insta 12-5-66. 18. I hereby certify that the form	a 20 sack cement plug i plug across the 9-5/8" 5/8" casing at the surfa alled per NMOCC specific egoing is true and correct	Acting Acting Area Supt.	cut off casing. '. Placed a 10 sack illed with mud. A ed and abandoned 	
<pre>off at 5090'. Placed Placed 40 sack cement cement plug in the 9-5 steel marker was insta l2-5-66.  18. I hereby certify that the for SIGNED</pre>	a 20 sack cement plug i plug across the 9-5/8" 5/8" casing at the surfa alled per NMOCC specific alled per NMOCC specific tite office use)	Acting	cut off casing. '. Placed a 10 sack illed with mud. A ed and abandoned 	
off at 5090'. Placed Placed 40 sack cement cement plug in the 9-5 steel marker was insta 12-5-66. 18. I hereby certify that the for SIGNED	a 20 sack cement plug i plug across the 9-5/8" 5/8" casing at the surfa alled per NMOCC specific defined per NMOCC specific state office use) TITLE	Acting Area Supt. ARR 2	cut off casing. '. Placed a 10 sack illed with mud. A ed and abandoned DATE 12-13-66	
<pre>off at 5090'. Placed Placed 40 sack cement cement plug in the 9-5 steel marker was insta l2-5-66.  18. I hereby certify that the for SIGNED</pre>	a 20 sack cement plug i plug across the 9-5/8" 5/8" casing at the surfa alled per NMOCC specific defined per NMOCC specific state office use) TITLE	Acting Area Supt. ARR 2	cut off casing. '. Placed a 10 sack illed with mud. A ed and abandoned DATE 12-13-66 <b>IDATE</b> 1967 RDON	

	, DEPARTI	LENITED STATES	RIOR (Other Instruction on a stress side)	
	C	GEOLOGICAL SURVEY	5. 6. 6.	MA-047651-8
		ICES AND REDORTS	ON WELLSE	6. IF INDIAN, ALLOTTEL OR TRIBE
1. OIL WELL X GAS WELL WELL	OTHER	<u>AUS 3</u>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	· · · · ·		· · · · · · · · · · · · · · · · · · ·	S. FARM OR LEASE NAME
3. ADDRESS OF GPERATO		n Oil Company	······	9. WELL NO.
		ax 220, Hobbs, New M	exico	1
4. LOCATION OF WELL (I See also space 17 bel		learly and in accordance with an	y State requirements.*	10. FIELD AND POOL, ON WILDCAT
At surface	660' FS	L and 1980' F%L		Allison Ponn 11. sec., r., r., M., on Elk. And server of Anta
				Sub. 21-85-370
14. PERMIT NO.		15. ELEVATIONS (Show whether I	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STAT
·····		DF 4051'		Roosevelt New 1
16.	Check Ar	opropriate Box To Indicate	Nature of Notice, Report, or	Other Data
	NOTICE OF INTEN	TION TO:	SUBSI	EQUENT REPORT OF:
TEST WATER SHUT-O	FI	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	;	ABANDON* X	SHOUTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL (Other)		CHANGE PLANS	(Other)	its of multiple completion on Well
17. DESCRIBE PROPOSED OF	i well is direction	RATIONS (Clearly state all pertine maily drilled, give subsurface loc	ent details, and give pertinent date	pletion Report and Log form.) es, including estimated date of starti- ical depths for all markers and zones
We propose to p	olug and a	bandon this well, in	n accordance with app	roved methods.
commensing appr	roximately	September 15, 1966.	. Plan to spot a 25	sack coment plug
commensing appr	roximately	September 15, 1966.		sack coment plug
commenting appr in the Bough "C	roximately C <sup>n</sup> section	September 15, 1966. (open hole) 9476-99	. Plan to spot a 25	sack compart plug
commencing appr in the Bough "C off at approx.	coximately C <sup>n</sup> section 6500'; pl.	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement	• Flan to spot a 25 509' in the 7" casing	sack compart plug ;; cut ?" casing -5/3" casing at
commenting appr in the Bough "C off at approx. 4205'. Set off	roximately D <sup>n</sup> section 6500'; pl her plugs a	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary,	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9	sack compart plug ;; cut ?" casing -5/3" casing at : pluge will be
commenting appr in the Bough "C off at approx. 4205'. Set off	roximately D <sup>n</sup> section 6500'; pl her plugs a	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary,	• Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 • All spaces between	sack compart plug ;; cut ?" casing -5/3" casing at : pluge will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with mud installed.	roximately 2" section 6500'; pl her plugs a d laden flu	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel narke:	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOCC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with mud installed.	roximately 2" section 6500'; pl her plugs a d laden flu	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel marker O-foot plugs to be	• Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 • All spaces between	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with mud installed.	roximately D' section 6500'; pl. her plugs a d laden flu	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel marker O-foot plugs to be	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOCC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with mud installed.	roximately D' section 6500'; pl. her plugs a d laden flu	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel marker O-foot plugs to be	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOCC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with mud installed.	roximately D' section 6500'; pl. her plugs a d laden flu	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel marker O-foot plugs to be	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOCC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with mud installed.	roximately D' section 6500'; pl. her plugs a d laden flu	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel marker O-foot plugs to be	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOCC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with mud installed.	roximately D' section 6500'; pl her plugs a d laden flu d laden flu <b>cf Abo fo</b>	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel narke: O-foot plugs to be a rmtions.	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOCC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with muc installed. MENDMENT: Adds top	roximately D' section 6500'; pl her plugs a d laden flu d laden flu <b>cf Abo fo</b>	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel narker O-foot plugs to be a rmations.	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOCC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with mud installed. MENDMENT: Add top	the foregoing is	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel narker O-foot plugs to be a rmations.	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOOC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set oth filled with muc installed. MENDMENT: Adds top	the foregoing is	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary. uid. A steel marker O-foot plugs to be a restions.	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOOC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set off filled with muc installed. MENDMENT: Addi top	the foregoing is	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary. uid. A steel marker O-foot plugs to be a restions.	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOOC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set oth filled with muc installed. MENDMENT: Adds top	the foregoing is	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary. uid. A steel marker O-foot plugs to be a restions.	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOOC specifica	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be
commencing appr in the Bough "C off at approx. 4205'. Set oth filled with muc installed. MENDMENT: Adds top	the foregoing is	September 15, 1966. (open hole) 9476-99 ace a 25 sack cement as deemed necessary, uid. A steel narker O-foot plugs to be a rmations.	. Flan to spot a 25 509' in the 7" casing t plug in bottom of 9 . All spaces between r per NMOOC specifica . All <b>Specifica</b> . All <b>Specif</b>	sack compatiplug ;; cut ?" casing -5/3" casing at : plugs will be tions will be

NUMBER OF COPIES RECEIVED				······································				
	NEW MEXICO OI	L CONSERVAT	FORM C-110					
PiLE U.B.G.3.	SANTA FE, NEW MEXICO (Rev. 7-60)							
	CERTIFICATE OF COMPLIANCE AND AUTHORIZATION							
PROBATION OFFICE								
OF EAATOR								
Company or Operator Lease FM T1 AM 10 29 Well No.								
Marathon Oil Company			Silver "D					
Unit Letter Section Township	County							
N 21 8-5	E Roosevelt							
Allison Penn.			Kind of Lease (State, Fed, Federal	ee)				
If well produces oil or condensate give location of tanks	Unit Letter N	Section 21	Township 8-S	Range 37-F				
Authorized transporter of oil [X] or condensate			dress to which approved copy	of this form is to be sent)				
McWood Corporation 701 V & J Tower, Midland, Texas								
Is Gas A	ctually Connecte	d? Yes X	No	,, _,, _				
Authorized transporter of casing head gas X or dry gas		†	dress to which approved copy of	of this form is to be sent)				
Sinclair Oil and Gas Company	8-6-60	Box 308, Midland, <sup>1</sup> exas						
If gas is not being sold, give reasons and also explain its	present disposition:	[						
REASON(S) FOR FILING (please check proper box)         New Veil								
The undersigned certifies that the Rules and Regulations of the Oil Conservation Commission have been complied with.								
Executed this the 29th day of July , 19 63.								
OIL CONSERVATION COMMISSION								
Approved by		Tide Asst	. Supt.					
The Contract of the Contract o		Company	thon Oil Company					
Date		Address Box	220, Hobbs, New M	exico				