

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.

LC-060521-A

INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		2. NAME OF OPERATOR J.M. Huber Corporation		3. ADDRESS OF OPERATOR 1900 Wilco Bldg., Midland, Texas 79701		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL, 1980' FEL Sec. 17, T8S, R36E		5. ELEVATIONS (Show whether DF, RT, GR, etc.) KB: 3535' GR: 3524'		6. PERMIT NO.		7. FIELD AND POOL, OR WILDCAT Prairie, S. (San Andres)		8. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 17, T8S, R36E		9. COUNTY OR PARISH Roosevelt		10. STATE New Mexico	
--	--	---	--	--	--	--	--	--	--	---------------	--	---	--	--	--	----------------------------------	--	-------------------------	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Abandon Bough "C" interval from 9688'-92' by setting CIBP at 7800'. Cap w/35' cement.
2. Perf. 5½" csg at 5300' set cement retainer at 5248'. Pump 400 sx. cement. TOC 4770'.
3. Perforated San Andres 4980'-4995' w/4 jet shots per foot. Acidize w/15 bbls acid.
4. Put well on pump.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Production Mngr DATE 8-30-82

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL

ACCEPTED FOR RECORD

PETER V. CHESTER

SEP 29 1983

TITLE

DATE

*See Instructions on Reverse Side