

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
reverse side)

TE-
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

62519

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Intention to Plug and Abandon		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Brace Burn Petroleum Corporation		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR c/o Oliver & West, Inc. 211 No. Ervay, Dallas, Texas		8. FARM OR LEASE NAME Federal - Selman	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' from S line; 660' from E line of Sec. 24		9. WELL NO. One	
10. FIELD AND POOL, OR WILDCAT Blunt Penn.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24; T8S; 36E, NWPM	
14. PERMIT NO. Unknown	15. ELEVATIONS (Show whether DF, RT, CR, etc.) 4073 K B	12. COUNTY OR PARISH Roosevelt	13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☒
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Due to well having reached its economical limits in production, propose to plug and abandon. To be plugged as outlined below:

20 sack plug from 9,351 to total depth
20 sack plug in and out at 5 1/2" casing stub (if casing is cut and pulled)
20 sack plug at 6,500' (top of Tubn)
30 sack plug in and out of 8 5/8" casing shoe
30 sack plug in and out of 8 5/8" casing stub (if casing is cut and pulled)
40 sack plug in and out of 10 3/8" casing shoe
20 sack plug at top of 10 3/8" casing
Ten pound mud shall be placed between all plugs.
A regulation marker, with well number and location, shall be placed in the top cement plug and the location cleaned and leveled to original contour of the surface.

18. I hereby certify that the foregoing is true and correct.
SIGNED C. L. Fuqua TITLE Agent DATE June 11, 1965
(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUN 15 1965

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.