

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec NM 87410

OIL CONSERVATION DIVISION
P.O. BOX 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>00243</u> 30-041-10047
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Milnesand Unit
8. Well No. 162
9. Pool name or Wildcat Milnesand (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> INJECTION	
2. Name of Operator MAERSK ENERGY Inc.	
3. Address of Operator 2424 Wilcrest, Suite 200, Houston, TX 77042-2753	
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line SE SE Section <u>12</u> Township <u>8S</u> Range <u>34E</u> NMPM _____ County <u>Roosevelt</u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4241.0'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, Or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: _____ <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <u>CLEAN-OUT, REPERFORATE AND STIMULATE</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Work Described: Thru tubing clean-out, reperforating & stimulation of San Andres Injection Well
Work Commenced: 05/17/93
Work Completed: 05/19/93

Operations Detail:

- 1) Cleaned-out well to 4635' with coiled tubing.
- 2) Spot 220 gallons of S444 Calcium Sulfate Converter Chemical.
- 3) Perforate San Andres with 4 SPF from:
4533' - 4537' 4561' - 4573'
4540' - 4544' 4614' - 4628'
4551' - 4556'
- 4) Acidize San Andres perms with 2500 gallons of 15% HCL acid.
- 5) Place well back in service.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE GASLCC TITLE DRILLING MANAGER DATE May 28, 1993
TYPE OR PRINT NAME GEORGE SHEFFER TELEPHONE NO. 713/783-0376

(This Space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUN - 4 1993