

P.O. BOX 1980

HOBBS, NEW MEXICO 88240

Form 3160-5  
(July 1989)  
(Formerly 9-331)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTCONTACT RECEIVING  
OFFICE FOR NUMBER  
OF COPIES REQUIRED  
(Other instructions on re-  
verse side)BLM Roswell District  
Modified Form No.  
NMD60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

LC 062178

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Breck Operating Corp.

3a. Area Code &amp; Phone No.

(817) 559-3355

3. ADDRESS OF OPERATOR

P. O. Box 911, Breckenridge, TX 76424

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below)  
At surface

Unit Letter "A"; 660' FNL &amp; 660' FEL

7. UNIT AGREEMENT NAME

Milnesand Unit

8. FARM OR LEASE NAME

9. WELL NO.

57

10. FIELD AND POOL, OR WILDCAT

Milnesand (San Andres)

11. SEC., T., R., M., OR BLK. AND

Sec. 24, T-8S, R-34E

14. PERMIT NO.

15. ELEVATIONS (Show whether of, AT, GR, etc.)

4242' (DF)

12. COUNTY OR PARISH

Roosevelt

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANT

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Set CIBP &amp; cmt

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/30/91: MIRU Ice Well Service. POOH & LD 175 5/8" rods & 150 jts  
2-3/8" tbgs. RDMO.  
7/ 1/91: MIRU WL Mast Unit. RIH w/ GR to 4500'. Set 4-1/2" CIBP @  
4500' w/ 3sx cmt on top. RDMO.ACCEPTED FOR RECORD  
PETER W. CHESTER

JUL 30 1991

BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA

JUL 15 1991

18. I hereby certify that the foregoing is true and correct

SIGNED

Belinda Lawler

TITLE Production Clerk

DATE 7-11-91

(This space for initials or State seal)

APPROVED BY

FILED

DATE