

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
ND60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. UNIT AGREEMENT NAME Milnesand Unit
2. NAME OF OPERATOR Breck Operating Corp.		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR P. O. Box 911, Breckenridge, TX 76424		9. WELL NO. 510
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter "C"; 660' FNL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT Milnesand (San Andres)
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 13, T-8S, R-34E
15. ELEVATIONS (Show whether of, RT, GR, etc.) 4263' (DF)		12. COUNTY OR PARISH 13. STATE Roosevelt NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☐
CHANGE PLANT ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) Set CIBP & cmt


REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/5/91: MIRU Ice Well Service. POOH & LD 40 rods. SDFWE.

7/8/91: POOH & LD rem rods. Total: 184 3/4" rods. POOH & LD 150 jts
2-3/8" tbg. RIH w/ GR to 4500'. Set 4-1/2" CIBP on WL @
4500' w/ 3 sx cmt on top. RDMO.



JUL 15 1991

18. I hereby certify that the foregoing is true and correct

SIGNED Belinda Lawler
Belinda Lawler

TITLE Production Clerk

DATE 7-11-91