

Form 3160-5
(July 1989)
(Formerly 9-331)

N. M. OIL CONS. COMMISSION

P. O. BOX 1980

HOBBS, NEW MEXICO 88240

UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUM
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NM60-3160-4

3. LEASE DESIGNATION AND SERIAL NO.

LC 062178

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Milnesand Unit

8. FARM OR LEASE NAME

9. WELL NO.

513

10. FIELD AND POOL, OR WILDCAT

Milnesand (San Andres)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 24, T-8S, R-34E

12. COUNTY OR PARISH

Roosevelt

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for each proposal.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW

2. NAME OF OPERATOR
Breck Operating Corp.

3a. Area Code & Phone No.
(817) 559-3355

3. ADDRESS OF OPERATOR
P.O. Box 911 Breckenridge, TX 76024

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit Letter "H"; 1980' FNL & 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DI, RT, GR, etc.)

4242' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent
to this work.)*

Breck Operating Corp. is planning to plug & abandon the subject well.
Please see the attached wellbore diagrams for the present status and
proposed status. The BLM representative will be notified in sufficient
time to witness all P&A operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

Kevin G. Duncan
Kevin G. Duncan

TITLE

Petroleum Engineer

DATE

4-12-91

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*Additional plug needed
1800' - 1690'*

*See Instructions on Reverse Side

APPROVED
DATE PETER W. CHESTER
MAY 1 1991
BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

MILNESAND UNIT #513
MILNESAND (SAN ANDRES) FIELD
ROOSEVELT COUNTY, NEW MEXICO

EXISTING STATUS

SURFACE CASING: 8-5/8" 24# @ 357' w/25# ss cml in 12-1/4" hole. Cml c/c/c.

PRODUCTION CASING: 4-1/2" 9.5# @ 4730' w/250# ss cml in 7-7/8" hole. TOC @ 3940'.

PERFORATIONS: 4622-4682.

TD: 4730'.

P8TD: 4695'.

PREVIOUS WORKOVERS

6/27/86: 5 qtz csg leak @ 1692-1755.

11/5/90: Attempt to sqz csg leak @ 1050-1784' w/200# ss Prim Plus cml w/no success. Sqz again w/20# ss Matrix cml w/no success.

KGD
4/11/91

MILNESAND UNIT #513
MILNESAND (SAN ANDRES) FIELD
ROOSEVELT COUNTY, NEW MEXICO

PROPOSED STATUS

1. Set CIBP @ 4590' above perfor @ 4622-4682' & dump 3 ss cml on top of CIBP from 4550-4515'.
2. Load hole w/9.5# mud.
3. Cut csg @ 357' & P00H. Pump 35 ss cml from 407-307' across csg shoe @ 357'.
4. Cut off csg 3' below GR. Dump 15 ss cml from 53-3'. Weld on plate & cement dry-hole marker.

** Cemented and jetting mud.*
16CC - 1650'

APPROVED
PETER W. CHESTER
Peter W. Chester
MAY 1 1991
BUREAU OF LAND MANAGEMENT
ROOSEVELT RESOURCE AREA

APR 17 1991

KGD
4/11/91