

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NMO60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
LC 062178

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Milnesand Unit

8. FARM OR LEASE NAME

9. WELL NO.
514

10. FIELD AND POOL, OR WILDCAT
Milnesand (San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec 24, T-8S, R-34E

12. COUNTY OR PARISH 13. STATE
Roosevelt NM

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR
Breck Operating Corp.

3a. Area Code & Phone No.
(817) 559-3355

3. ADDRESS OF OPERATOR
P. O. Box 911, Breckenridge, TX 76424

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below)
At surface

Unit Letter "J"; 1980' FSL & 1980' FEL

14. PERMIT NO. 15. ELEVATIONS (Show whether OF, RT, CR, etc.)
4241' (DF)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANT ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐


Set CIBP & cmt ☒

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

6/27/91: MIRU Ice Well Service. POOH & LD 182 3/4" rods & 95 jts
2-3/8" tbg. CWI.

6/28/91: FOOH w/ tbg. Total: 149 jts 2-3/8" tbg. RDMO. MIRU WL
Mast Unit. RIH w/ GR to 4600'. Set 4-1/2" CIBP @ 4600'
w/ 3 sx cmt on top. RDMO.



JUL 18 1991

18. I hereby certify that the foregoing is true and correct.

SIGNED Belinda Lawler
Belinda Lawler

TITLE Product Area Clerk

DATE 7-11-91