

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back a well or to
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. MI-02218	
2. NAME OF OPERATOR David Fackel		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 608 First Natl. Bank Bldg., Midland, Texas		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit N, 1980' FWL & 810' FSL		8. FARM OR LEASE NAME King-Davis "A" Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4016.8 GR		10. FIELD AND POOL, OR WILDCAT Allison (Perm)	
		11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA Sec. 33, T-8-S, R-37-E	
		12. COUNTY OR PARISH Roosevelt	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Squeeze Perforations ☒	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

(This well was formerly Jos. I. O'Neill, Jr. #1 Federal "J")

1. Pulled 306 joints 2-3/8", J-55, HUE, 8rd Tubing.
2. Set retrievable bridge plug at 9566'.
3. Set DM squeeze tool at 9435'.
4. Squeezed Bough "B" perforations 9540-52 w/100 sacks Incor Neat. Max. Sq. Press. 5000 psig.
5. Set RITS at 8600' and squeezed Abo perforations (8925-47) with 200 sacks. Max. Sq. Press. 4500 psig.
6. Drilled cement and DM plug and tested perforations to 1500 psig.
7. Swab tested both sets of perforations. Test was dry.
8. Pulled retrievable bridge plug.
9. Installed hydraulic pump on 2-3/8" tubing and put well on production.

RECEIVED
DEC 22 1966
U. S. GEOLOGICAL SURVEY
ROOSEVELT, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Robert H. Angevine TITLE Agent DATE 12/19/66

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
DEC 23 1966
A. R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

807-351

Dec 58 15 28 AM '88
U.S. GOVERNMENT PRINTING OFFICE