

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>5. State Oil &amp; Gas Lease No. <b>E 0913</b></p>
<p>2. Name of Operator <b>Cactus Drilling Company</b></p>		<p>7. Unit Agreement Name</p>
<p>3. Address of Operator <b>Drawer 2068, Hobbs, New Mexico</b></p>		<p>8. Farm or Lease Name <b>State ID!</b></p>
<p>4. Location of Well UNIT LETTER <b>P</b> <b>660</b> FEET FROM THE <b>So</b> LINE AND <b>660</b> FEET FROM <b>Ea.</b> <b>28</b> LINE, SECTION <b>7 S</b> RANGE <b>36 E</b> NMPM.</p>		<p>9. Well No. <b>1</b></p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) <b>4128 D F</b></p>		<p>10. Field and Pool, or Wildcat <b>Wildcat</b></p>
		<p>12. County <b>Roosevelt</b></p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	



17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perforations were made in 4 1/2" casing 4468-4443' and no production attainable. we propose to plug and abandon the well in the following manner:

Set 15 sx cement plug 4440-4470; set 25 sx cement plug at shoot-off point; set 25 sx cement plug at 2240; 25 sx cement plug in and out of 8-5/8 set at 365' D.F.; and 10 sx cement plug set at surface. All intervals between plugs to be filled with mud. Lease location will be cleared of all equipment and well site returned to normal contour. Appropriate well marker identifying the location will be set.

Oral permission granted this day to proceed with above work by Mr. Joe D. Ramsey.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  TITLE Production Supt. DATE June 10, 1965  
APPROVED BY  TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: