

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2734

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well	7. Unit Agreement Name State 32-7-33
2. Name of Operator Champlin Petroleum Company	8. Farm or Lease Name
3. Address of Operator 300 Wilco Building Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER B, 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 7-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Chaveroo-San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4420' Gr.	12. County Roosevelt

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was Plugged and Abandoned as follows:

4-26-77 Set CIBP 4270'.
4-27-77 Dumped 50' cement on CIBP.
4-27-77 Perforated 4-1/2" casing @1750'. Squeezed 40 sxs. cement to 1650' thru packer. Left 100' plug inside 4-1/2" casing.
4-27-77 Shot casing @473' pulled 473' of 4-1/2" casing.
4-28-77 Set 10 sack plug in top of surface.
Installed Dry Hole Marker.
Hole loaded with 10# Mud w/gel.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Walter M. Crandall</u>	TITLE <u>District Clerk</u>	DATE <u>May 27, 1977</u>
APPROVED BY <u>Eddie Dean</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>APR 2 1979</u>
CONDITIONS OF APPROVAL, IF ANY:		