

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>	7. Unit Agreement Name
2. Name of Operator <b>Cities Service Oil Company</b>	8. Farm or Lease Name <b>Pate A</b>
3. Address of Operator <b>P.O. Box 69 - Hobbs, New Mexico</b>	9. Well No. <b>8</b>
4. Location of Well UNIT LETTER <b>P</b> , <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>7</b> TOWNSHIP <b>8S</b> RANGE <b>35E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Milnesand San Andres</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4239 DF 4231 Gr.</b>	12. County <b>Hessavalt</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was drilled to a T.D. of 4734 Dolomite. No oil of commercial quantity was found so the above well was plugged and abandoned in the following manner:

1. Hole was loaded w/mud.
2. Set a 25 sack cement plug @ 4734-4653.
3. Set a 25 sack cement plug @ 2652-2571.
4. Set a 25 sack cement plug @ 2240-2179.
5. Set a 25 sack cement plug @ 450-369.  
(33' below and 48' above bottom of 8 5/8" surface cng.)
6. Set a 10 sack cement plug @ 40'-base of cellar.
7. Installed a 3" marker 4' above ground.
8. Location has been cleared of all equipment and debris, pits have been filled and leveled.

Location is now ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>W. Robertson</u>	TITLE <b>District Clerk</b>	DATE <b>3-23-65</b>
APPROVED BY <u>Leslie A. Clements</u>		
CONDITIONS OF APPROVAL, IF ANY:		