orm.	9-33.	
May	1963	١

P. O. BOX 1980. TATES

		Form a Budget	pprove Bures	ea. 11 N	o. 42-R	142
5.	LEASE	DESIGN	ATION	AND	BERLAL	NO.

orm 9-33. May 1963)	D.HOB!	35 NEW MAL - DO 85749 -	RIOR (Other instructions on verse side)	Budget Bureau No. 42-R14 5. LEASE DESIGNATION AND SERIAL N	
	DEPAR	GEOLOGICAL SURVEY	ALION Verse Buch	LC 060978	
				6. IF INDIAN, ALLOTTEE OR TRIBE NA	ME
9	SUNDRY N	OTICES AND REPORTS	ON WELLS RECEIVED		
(Do not use	this form for programmer that the third that the th	roposals to drill or to deepen or plu LICATION FOR PERMIT—" for suc	ng back to a different'résérvoir.	100	
l.			NCT 3 13 48 51	T. UNIT AGREEMENT NAME	
oir X &	AS OTHE	SR.	201	Milnesand (SA) Unit	
2. NAME OF OPERA			Biggin	8. PARM OR LEASE NAME	
UNION	TEXAS PET	ROLEUM CORPO.	RUST, and the		
3. ADDRESS OF OPE				9. WELL NO.	
1400	Wilco Bldg	Midland, TX 79701		316	
4. LOCATION OF WE See also space 1	LL (Report locat	ion clearly and in accordance with	any State requirements.*	10. FIELD AND POOL, OR WILDCAT	
At surface	. i delowiy			Milnesand	
				11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA	
				19	
Unit Let	ter "N" <u>, 9</u>	90' FSL & 1654.5' FWL		Sec. 18, T8S, R35E	
14. PERMIT NO.		15. ELEVATIONS (Show whether		12. COUNTY OR PARISH 13. STATE	
		4231' GR, 4239.5	' KB	Roosevelt NM	
16.	Check	Appropriate Box To Indicat	e Nature of Notice, Report, or C	Other Data	
	NOTICE OF	INTENTION TO:	• STBSEQ	CENT REPORT OF:	
TEST WATER S	HITTORE	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TRE	1	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OF ACI		ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* X	
REPAIR WELL		CHANGE PLANS	(Other)		
(Other)			(Norr: Report results Completion or Recomp	s of multiple completion on Well pletion Report and Log form.)	
17. DESCRIBE PROPE proposed wo nent to this	ork. If well is d	n operations (Clearly state all pertirectionally drilled, give subsurface	inent details, and give pertinent dates locations and measured and true vertic	, including estimated date of starting and depths for all markers and zones ;	ar pert
2	Sept. 23, 1		ed wellhead, installed Bement on top. RIH w/2 3		

- hole w/10# mud laden gel.
- Sept. 24, 1983 Perf. 4 1/2" csg. @ 2235' w/4 holes, Set cement retainer at 2135' squeezed w/30 sx. Class "C", PO of retainer and dumped 10 sx. cement on top. Perf. 4 1/2" csg. @ 420'
 Set cement retainer @ 320' - tested csg. to 500 psi - csg. held. Stung into retainer, established circ. and cemented to surf. w/100 sx. Class "C".
- Sept. 25, 1983 Removed BOP, set 50' cement plug at surf. Cut off 4 1/2" csg. Welded steel plate across csg. - set dry hole marker and cleaned up location - WELL NOW P&A.

15. I hereby certify the foregoing is true and correct		
SIGNED/ Slight St. Hoggin	TITLE Prod. Services Supr.	DATE 9-30-83
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	APPROVED PETER W. CHESTER
* \$	ee Instructions on Reverse Side	MAY 3 1985 BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA

MAY 8 1985