

FIELD: WINESTON (SAN ANDRES)

PROCEDURE

LEASE: NIENHARD WELL NO. 515

DATE: 2-83 SPUDDED: _____ COMP. 1984

ELEV: 4239.5 KR 8' AGL

LOCATION: 990' FSL AND 1654' FWL

SECTION 10 T-9-S K-35-S

POSSIBLE - Common New Mexico

50' Plug AT SURFACE

CEMENT RETAINER AT 300' CEMENTED TO SURFACE WITH 100 S. CLASS C

24 # 5 5/8" CSG. OF 363 W/ 225 SX. CLASS "C"
" HOLE TOC SURFACE

PERFS AT 420'

SHALLOW CASING LEAK

CEMENT RETAINER AT 2135 CEMENTED WITH 30 SXS CLASS C

PERFS 2235

TOC - ESTIMATED 4000'

CIBP AT 4595' WITH 35' OF CEMENT ON TOP

PERFS 4646-4686
4702-4714

10.5 # 4 1/2" CSG. OF 4730 W/ 300 SX. CLASS "C"
" HOLE TOC UNKNOWN

TO 4730
PETO 4735

H. M. OIL CONG. COMMISSION
UNITED STATES P. O. BOX 50000
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NA LC-060978

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Union Texas Petroleum Corp.

3. ADDRESS OF OPERATOR

1400 Wilco Bldg., Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit Letter "N", 990' FSL & 1654.5' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, GR, etc.)

4231' GL, 4239.5' KB

7. UNIT AGREEMENT NAME

Milnesand (SA) Unit

8. FARM OR LEASE NAME

9. WELL NO.

316

10. FIELD AND POOL, OR WILDCAT

Milnesand

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 19, T-8-S, R-35-E

12. COUNTY OR PARISH

Roosevelt

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Remove wellhead, install BOP.
2. Set CIBP on wireline @ 4595'. Dump 35' of cement on CIBP.
3. Perf. 4 1/2" csg. w/4 holes @ 2235'. Set retainer @ 2135'.
4. RIH w/2 3/8" tbg. and sting into retainer. Cement w/30 sx. Class "C" 2135'-2235' across top of Rustler.
5. Pull up, spot 10 sx.cement above retainer. POH w/tbg.
6. Perf. 4 1/2" csg. @ 420'. Set retainer @ 320'.
7. Test csg. to 500 psi. If press. does not leak off, sting into retainer, open braden head and attempt to establish circ.
8. Pump 100 sx. Class "C" cement and circ. to surf. POH w/tbg.
9. Remove BOP. Spot 50' plug of cement at surf. Cement thru 1" tbg. down backside if cement did not circ. in Step #8.
10. Cut off csg., weld on steel plate and set marker. RDSU and clean up location.

RECEIVED
MAY 1983

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Prod. Services Supr.

DATE

4-18-83

(This space for Federal or State office use)

APPROVED BY

(Orig Sgd.) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 25 1983