

UNITED STATES
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLE
(Other instructions
reverse side)

E*
re-

Form approved,
Budget Bureau No. 42 R1424.

GEOLOGICAL SURVEY

LEASE DESIGNATION AND SERIAL NO.

LC 062529-A

INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. LEASE AGREEMENT NAME	
2. NAME OF OPERATOR FRANKLIN, ASTON & FAIR, INC.		8. FARM OR LEASE NAME Mark Federal	
3. ADDRESS OF OPERATOR P. O. Box 1090, Roswell, New Mexico 88201		9. WELL NO. 4	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FML & 1650' FEL Section 25-7S-35E		10. FIELD AND POOL, OR WILDCAT Todd Upper San Andres	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25-7S-35E, NMPM	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4181' GR		12. COUNTY OR PARISH Roosevelt	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

Temporarily Abandoned

X

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On December 27, 1966 set wire line bridge plug at 4218' and dumped 1/2 sack cement on top. This is above perforations at 4235' to 4269' in the Todd Lower San Andres which had ceased to produce. The Todd Upper San Andres was perforated one shot at 4131', 4139', 4157', 4162', 4173', 4180', 4184', 4196', 4206', 4211', and acidized with 6,000 gallons acid. Well snubbed dry with very slight show of gas. The rods and tubing were pulled and the well temporarily abandoned with a 1 1/2 to 2 swage and valve at surface. It is anticipated that this well may be used as an injection well should the Todd Lower San Andres ever be water flooded.

18. I hereby certify that the foregoing is true and correct

SIGNED Grant M. Smith

TITLE Geologist

DATE January 20, 1967

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.