FILE	DISTRIBUTION		Form C-103 Supersedes Old C-102 and C-103
D.S. 0.8. So. Indicates Type of Lense CAND OFFICE So. Indicates Type of Lense OPERATOR State Oil 6 Gas Lesse No. North Superior State Control of Complete Control of Complete Control of Cont of Control of Con	SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
0.0.0.3. State (2)	FILE	-	
S. Biote OIL & Construction S. Biote OIL & Gras Leave No. S. Biote OIL & Gras Leave No. K-2610 Support of Construction of the set of th	U.S.G.S.		
K-2610 SUNDRY NOTICES AND REPORTS ON WELLS K-2610 K-2610 SUNDRY NOTICES AND REPORTS ON WELLS (In nor use this gradule and colspan="2">K-2610 Norme of Committie Norme of Committie Tom L, Ingram Norme of Committie Tom L, Ingram Norme of Committie Norme of Leare Norme Norme of Committie Norme of Leare Norme Norme of Committie	LAND OFFICE		State XX Fee
SUNDRY NOTICES AND REPORTS ON WELLS (In the sector of	OPERATOR		-
(c) Note of the proceeded PERMIT-SM PROCEEDING Colspan="2">Colspan="2"Colspan=			K-2610
(c) Note of the proceeded PERMIT-SM PROCEEDING Colspan="2">Colspan="2"Colspan=	SUNDE	AND REPORTS ON WELLS	
VIL.L XX WELL OTHER- 7. Unit Agreement Nome Nome of Operator 7. Unit Agreement Nome 7. Unit Agreement Nome Tom L. Ingram 8. Form or Lease Name State Address of Operator 9. Well No. 9. Well No. POB 1757, Roswell, New Mexico 88201 1 1 Location of Well 10. Fleid and Pool, or Wildeat 10. Fleid and Pool, or Wildeat Unit LETTER C 660 ret ream ret North 1980 The West 32 TOWNSHIP 85 RANGE The Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Norther DF: NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUE AND ABANDON RemediaL work Altrenine casing PULE ON ALTER Casing Charles Plans Charles Plans OTHER Charles Plans Charles Plans Charles Plans OTHER Charles Plans Charles Plans Charles Plans The Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Notice Constance Charles Plans Other Note Plans Charles Plans Charles Plans Other	(DI) NOT USE THIS FORM FOR POR	»	
Other of Coperator 9. Form of Leone Name Tom L. Ingram 9. Well No. Address of Operator 9. Well No. POB 1757, Roswell, New Mexico 88201 1 Location of Well 10. Field and Pool, or Wildeet unit Letter 660 rec 9. Well No. 10. Field and Pool, or Wildeet with Letter 10. Field and Pool, or Wildeet rec West unit Letter 32 rec 388 rec 388 Is, Elevation (Show whether DF, RT, GR, etc.) 3980 KB Roosevelt Recording and exactors Roosevelt Recording and exactors Recording and exactors PLUE AND ABANDON SUBSEQUENT REPORT OF: recording and exactors Recording and exactors recording and exactors Charles Place recording and exactors Recording and exactor recording and exactor	l,		
Name of Coparation 8. Farm or Leave Name Tom L. Ingram State Address of Coparation 9. Well No. POB 1757, Roswell, New Mexico 88201 1 .Location of Well 9. Voil No. UNIT LETTER C .Location of Well 10. Field and Pool, or Wildow UNIT LETTER C .Location of Well 10. Field and Pool, or Wildow West 11. Elevation (Show whether DF, RT, GR, etc) The Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUB AND ABANDON Remedial work PLUB AND ABANDON Remedial work OTHER Chance Plans			
State State State State State State POB 1757, Roswell, New Mexico 88201 Interview of Operator North 10. Fleid and Pool, or Wildcat Weilt No. UNIT LETTER C 660 reter read, referend of the Line AND 1980 reter read, referend of the Direct read, referend of North Sawyer Devonia UNIT LETTER C 660 reter read, referend of the Direct read, referend of Weilt UNIT LETTER C 660 reter read, referend of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: State Direct of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent Report of: Colspan="2">ALTERING CASING Plug AND ABANDON THE ALTERING CASING Plug AND ABANDON THE		OTHER•	8 Farm of Lease Name
Address of Operation 9. Well No. POB 1757, Roswell, New Mexico 88201 1 Location of Well 1 UNIT LETTER C 660 FEET FROM THE North 1980 THE C 15. Elevation (Show whether DF, RT, GR, etc.) 3980 KB 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUE AND ABANDON PULL OR ALTER CASING OTHER OTHER OTHER OTHER PLUE AND ABANDON PLUE AND ABANDON PULL OR ALTER CASING OTHER OTHER OTHER OTHER OTHER PLUE AND ABANDON PULE AND ABANDON NOTE State RUL E '105. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' casing from 8,000', will set a 100'			
POB 1757, Roswell, New Mexico 88201 1 Location of Well C 660 North 1980 Location of Well State North 1980 North Sawyer Devoir a Location of Well State 85 RAMSE 38E North Sawyer Devoir a Location of Well Is. Elevation (Show whether DF, RT, CR, etc.) 12. County Roosevelt 12. County Location of Intention To: SUBSEquent Report or Other Data Rometoial work Remetoial work Altrenine Casing Location of Alter casing Plue And Asandon Plue And Asandon Remetoial work Altrenine Casing Location Proposed or Completed Operations (Clearly state all periment details, and give pertiment dates, including estimated date of starting any proposet work) stee Rule 100' state allo of stab of 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' casi, 100' plug 7560; 100' plug @ 5478. Location Proposed o	· · · ·		
I. Location of Well C 660 North 1980 North Sawyer Devonia West 10. Field and Pool, or Wildcat North Sawyer Devonia THE West 32 TOWNSHIP 85 RANCE 38E North Sawyer Devonia THE West LINE, SECTION 32 TOWNSHIP 85 RANCE 38E North Sawyer Devonia THE West LINE, SECTION 32 TOWNSHIP 85 RANCE 38E North Sawyer Devonia 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORABLE ARADON PLUG AND ABANDON REMEDIAL WORK ALTERING CASING THE OTHER Commence oniLLING OPHS. PLUG AND ABANDON REMEDIAL WORK TEMPORABLE ARADON PLUG AND ABANDON REMEDIAL WORK ALTERING CASING THE OTHER OTHER DUG AND ABANDON PLUG AND ABANDON 17. DESCribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting		· · · · · · · · · · · · · · · · · · ·	9. Well No.
In the left of a line of a line of a line and construction and constructine constructing and constructing constructing and constr	POB 1757, Roswell	, New Mexico 88201	1
West 32 32 385 38E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 12. County 3980 KB 12. County Roosevelt 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING PLUG AND ABANDON OTHER CHANGE PLANS OTHER OTHER Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', Will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	Location of Well		10. Field and Pool, or Wildcat
West 32 32 385 38E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 12. County 3980 KB 12. County Roosevelt 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING PLUG AND ABANDON OTHER CHANGE PLANS OTHER OTHER Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', Will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	C 6	60 North 1980	North Sawyer Devonia
THE LINE, SECTION TOWNSHIP NAME NMPM. 15. Elevation 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3980 KB Roosevelt 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUE AND ABANDON PULL OR ALTER CASING PLUE AND ABANDON OTHER CHANGE PLANS OTHER CHANGE PLANS IV. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of stub of 8-5/8 (a approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	UNIT LETTER	LINE AND	
THE TOWNSHIP ANGE NAME 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3980 KB Roosevelt 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON PUL OR ALTER CASING PLUG AND ABANDON OTHER CHANCE PLANS OTHER CHANCE PLANS 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 175S. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' csg; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of stub of 5½'' csg; 100' and pull. Will set 100' plug in & out of stub of 5½'' log base of 13-3/8 @ 403. Will set 10 sack plug	West	32 8S 38E	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING PUL OR ALTER CASING PLUG AND ABANDON ALTERING CASING PUL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER OTHER OTHER OTHER ALTERING any proposed 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see RULE 1103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of stub of 5½'' csg.; 100' plug @ 403. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	THE LINE, SECTI	ION TOWNSHIP RANGE	—— ^{имрм.} ())))))))))))))))))))))))))))))))))))
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING PUL OR ALTER CASING PLUG AND ABANDON ALTERING CASING PUL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER OTHER OTHER OTHER ALTERING any proposed 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see RULE 1103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of stub of 5½'' csg.; 100' plug @ 403. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	······································	15 Elemention (Show whether DE BT CR atc.)	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING ALTERING CASING PULL OR ALTER CASING PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQS ALTERING CASING OTHER CHANGE PLANS CHANGE PLANS OTHER PLUG AND ABANDONMENT OTHER CHANGE PLANS OTHER OTHER PLUG AND ABANDONMENT I7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see RULE 1103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER OTHER TOTHER USBERULE 1 FOS. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100 sack plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug		5300 Kb	- Koosevert
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB OTHER OTHER OTHER OTHER OTHER OTHER OTHER OTHER OTHER OTHER OTHER OTHER II. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	PERFORM REMEDIAL WORK	PLUG AND ABANDON	
OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RUL E 1103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull 5½'' casing from 8,000', will set a 100' plug in & out of stub of 5½'' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of 5½'' is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	FLUG AND ABANDONMENT
 OTHER	PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JO	الــا •
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull $5\frac{1}{2}$ '' casing from 8,000', will set a 100' plug in & out of stub of $5\frac{1}{2}$ '' csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of $5\frac{1}{2}$ '' is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug		OTHER	
<i>work)</i> SEE RULE 103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull $5\frac{1}{2}$ " casing from 8,000', will set a 100' plug in & out of stub of $5\frac{1}{2}$ " csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of $5\frac{1}{2}$ " is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	OTHER		
<i>work)</i> SEE RULE 103. Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull $5\frac{1}{2}$ " casing from 8,000', will set a 100' plug in & out of stub of $5\frac{1}{2}$ " csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of $5\frac{1}{2}$ " is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug			
Verbal approval from John Runyan on 11/13/74 (NMOCC). Set CIBP @ 11,300 with 35' cement plug on top. If able to pull $5\frac{1}{2}$ " casing from 8,000', will set a 100' plug in & out of stub of $5\frac{1}{2}$ " csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of $5\frac{1}{2}$ " is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	 Describe Proposed or Completed O work) SEE RULE 103. 	Operations (Clearly state all pertinent details, and give pertinent dates	, including estimated date of starting any propose
Set CIBP @ 11,300 with 35' cement plug on top. If able to pull $5\frac{1}{2}$ " casing from 8,000', will set a 100' plug in & out of stub of $5\frac{1}{2}$ " csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of $5\frac{1}{2}$ " is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug			
Set CIBP @ 11,300 with 35' cement plug on top. If able to pull $5\frac{1}{2}$ " casing from 8,000', will set a 100' plug in & out of stub of $5\frac{1}{2}$ " csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of $5\frac{1}{2}$ " is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	Verbal approval from	John Runyan on 11/13/74 (NMOCC).	
will set a 100' plug in & out of stub of $5\frac{1}{2}$ " csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of $5\frac{1}{2}$ " is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug			
will set a 100' plug in & out of stub of $5\frac{1}{2}$ " csg.; 100' plug @ 7560; 100' plug @ 5478. If stub of $5\frac{1}{2}$ " is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	Set CIBP @ 11.300 wit	h 35' cement plug on top. If able to pull	$1.5\frac{1}{2}$ casing from 8.000'.
If stub of $5\frac{1}{2}$ " is above any of these plugs, they will be omitted. Will set 100' plug in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug	will set a 100' plug	in ε out of stub of $5\frac{1}{2}$ (csa.: 100' plug @	7560: 100' plug @ 5478.
in & out of base of 8-5/8 at 4210. Cut 8-5/8 @ approx. 1000' and pull. Will set 100' plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug			
plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug		bove any of these progs, they will be omit	and multiplicate 100 plug
plug in & out of stub of 8-5/8; 100' plug @ base of 13-3/8 @ 403. Will set 10 sack plug @ surface and set marker. Mud laden brine to be used between all plugs. Clean location.			and DUIL. WILL SET IVU'
@ surface and set marker. Mud laden brine to be used between all plugs. Clean location.	in & out of base of 8	3-5/8 at 4210. Cut 8-5/8 @ approx. 1000 8	$\frac{1}{2}$
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug
	in & out of base of 8 plug in & out of stub	o of 8-5/8; 100' plug @ base of 13-3/8 @ 40	03. Will set 10 sack plug

. *** ;;	<u> </u>		
6. I hereby certify that the	he information above is true and compl	ete to the best of my knowledge and belief.	DATE 11/13/74
IGH Om			

RECEIVED

NON 1 4 1974 OIL CONSERVATION COMM. HOBBS, N. M.