Form 3160-5 November 1983) (Formerly 9-331)

Budget Bureau No. 1004-0135

UNITED STATES N. II. SUMMER 13. TOTAL SIGNATURE Budget Bureau No. 1004-013
Expires August 31, 1985
DEPARTMEN OF THE INTERIOR VERN MODELLA NO. 5. LEASE DESIGNATION AND SERIAL NO.

BUREAU OF LAND MANAGEMENT	HOBBS, NEVI MEXICO 8824	OLC-062178
SUNDRY NOTICES AND REPORTS C	JN WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL XX GAS OTHER	o o i nii Ugi	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	00n	Milnesand Unit 8. FARM OR LEASE NAME
Breck Operating Corp.	ROSWALL RESOURCE	
3. ADDRESS OF OPERATOR		9. WELL NO.
P.O. Box 911, Breckenridge, Texas 76	6024	42
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.		10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface		ilnesand (San Andres
Unit Letter 47, 1980' FSL & 660' FEL		11. SEC., T., E., M., OR BLE. AND SURVEY OR ARMA
$\mathcal{I}_{i}$		Sec. 14, T-8S, R-34E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF,		12. COUNTY OR PARISH 13. STATE
4273' KB	l <sub>R</sub>	Roosevelt New Mexic
		_
6. Check Appropriate Box To Indicate No Notice of Intention to:		ner Data
NOTICE OF INTENTION TO:	SUBSEQUE	T EMPORT OF:
NOTICE OF INTENTION TO:  TEST WATER SHUT-OFF PULL OR ALTER CASING	NUBSEQUE!	T REPORT OF:
NOTICE OF INTENTION TO:  TEST WATER SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE	SUBSEQUEN WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING
NOTICE OF INTENTION TO:  TEST WATER SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON* CHANGE PLANS  (Other) Set CIBP & Temp. Abandon X	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of	REPORT OF:  REPAIRING WELL  ALTERING CASING  ABANDONMENT*  multiple completion on Well  on Report and Log form.)
NOTICE OF INTENTION TO:  TEST WATER SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON*  REPAIR WELL CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other) (Note: Report results of	REPORT OF:  REPAIRING WELL  ALTERING CASING  ABANDONMENT*  multiple completion on Well on Report and Log form.)
NOTICE OF INTENTION TO:  TEST WATER SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON*  REPAIR WELL CHANGE PLANS  (Other) Set CIBP & Temp. Abandon X  7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent proposed work. If well is directionally drilled, give subsurface locations of the complete of the control of the contro	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other) (Note: Report results of	REPORT OF:  REPAIRING WELL  ALTERING CASING  ABANDONMENT*  multiple completion on Well on Report and Log form.)

## Procedure

Set 4-1/2" CIBP @ 4585'

Pressure up on casing to test downhole integrity.

Test to be conducted Wednesday, May 11, 1988

18. I hereby certify that the foregoing is true and correct SIGNED TWM J. JUMAN	TITLE Petroleum Engineer	DATE 4/20/88
(This space for Federal or State office use)		
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:  APPROVE ENDING *Se	ED FOR ANNTH PERIOD APR 25 1989  TITLE  APR 25 1989  TITLE	APPROVED PETER W. CHESTER  APR & 8 1988

Title to U.S.C. Section 1901, makes it a crime for any person knowingly and willfully to make to BURGARIOFILAND MANAGEMENT United States any false, fictitious or fraudulent statements or representations as to any matter within ROSWEGICLESOURCE AREX

MPR 29 1988

MOBBS OFFICE

HOBBS