

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side) 6:Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		5. LEASE DESIGNATION AND SERIAL NO. LC 065510
2. NAME OF OPERATOR JACK L. McCLELLAN		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 848, ROSWELL, NEW MEXICO		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 990' FSL & 1650' FWL		8. FARM OR LEASE NAME FEDERAL #22"
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4208.5 QL		10. FIELD AND POOL OR WILDCAT TODO SAN ANDRES
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA 28-T7S-R35E
		12. COUNTY OR PARISH ROOSEVELT
		13. STATE NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) SEGRGATE GAS ZONES	
(Other)		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/20/66 KILLED WELL & PULLED TUB. RE-RAN TUB. & SET PKR. AT 4197', TO SEPERATE THE "A" ZONE FROM THE "B" ZONE. TESTED "B" ZONE. WEAK BLOW OF GAS. WELL PROBABLY WATER LOGGED.

12/21/66 PULLED TUB. & SET BRIDGE PLUG @ 4195'. PERF. CSD. 1 SHOT/FT. AT 4158, 4160, 4168, 4170, 4180, 4182, & 4184, ALL IN THE "A" ZONE. SWB. LOAD MTR. HARD BLOW OF GAS.

12/22/66 FL 1500'. SWB. DOWN. ACIDIZED W/1000 GALS. (4158-4184). SWB. LOAD. FAIR TO GOOD BLOW OF GAS.

12/27/66 PULLED TUB. AND DRILLED OUT BRIDGE PLUG AT 4195'. RE-RAN TUBING AND SET PACKER AT 4195'.

ALTERNATELY TESTED "A" & "B" ZONE THROUGH TUBING AND CASING ANNULAS, TO ASCERTAIN WHICH ZONE PRODUCED MOST GAS.

WELL NOW PRODUCING GAS FROM THE "B" ZONE THROUGH THE TUBING, "A" ZONE SHUT-IN. PRESSURES ON TUBING AND CASING INDICATE THAT THE TWO ZONES ARE EFFECTLY SEPERATED.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jack L. McClellan

TITLE

Operator

DATE

3/15/67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

MAR 20 1967

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local, Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 5: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of setting of any casing liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1983-O-346228

4475-811

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS OF WELL

1. NAME OF OPERATOR ☒ FEDERAL ☐ STATE ☐ PRIVATE

2. ADDRESS OF OPERATOR

3. NAME OF WELL

4. LOCATION OF WELL (TOWNSHIP, RANGE, SECTION, COUNTY, STATE)

5. DEPTH OF WELL (FEET)

6. METHOD OF CLOSING TOP OF WELL

7. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION

8. REASON FOR ABANDONMENT

9. DATA ON FORMER OR PRESENT PRODUCTIVE ZONES, OR OTHER ZONES WITH PRESENT SIGNIFICANT FLUID CONTENTS NOT SEALED OFF BY CEMENT OR OTHERWISE

10. DEPTHS (TOP AND BOTTOM) AND METHOD OF PLACEMENT OF CEMENT PLUGS

11. MUD OR OTHER MATERIAL PLACED BELOW, BETWEEN AND ABOVE PLUGS

12. AMOUNT, SIZE, METHOD OF SETTING OF ANY CASING LINER OR TUBING PULLED

13. DEPTH TO TOP OF ANY LEFT IN THE HOLE

14. METHOD OF CLOSING TOP OF WELL

15. DATE WELL SITE CONDITIONED FOR FINAL INSPECTION

16. SIGNATURE OF OPERATOR

17. SIGNATURE OF BLM REPRESENTATIVE

18. DATE