UNITED STATES

5.	LEASE,	.1.1.		٠
	NM	1744	0,4568	5

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas other	Horton Federal
2. NAME OF OPERATOR	9. WELL NO. 27
Amoco Production Company	10. FIELD OR WILDCAT NAME
P. O. Box 68 Hobbs, NM 88240	Milnesand-San Andres
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	29-8 5 -35E
AT SURFACE: (UNIT G 1650' FNE X 2314' FEL, AT TOP PROD. INTERVAL: Sec. 29 T-8-S, R-35-E)	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Roosevelt NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES	rectionally drilled give subsurface locations and
Propose to increase production by the following. Pull rods and tubing. Drill out 20' to approx gallons in 2 stages. Install pumping equipmen	. 4738'. Acidize with 4000
Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED TITLE AST. Ad. Anal (This space for Federal or State office APPROVED BY TITLE CONDITIONS OF APPROVAL IF ANY: 1-USGS, H 1-HOU	yst _{DATE} 12-5-80

*See Instructions on Reverse Side

... Har DISTRICT SUPERVISOR