

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

OCT 22 1 23 PM '65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E - 1369

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Skelly Oil Company	8. Farm or Lease Name Hobbs "T"
3. Address of Operator P. O. Box 730 - Hobbs, New Mexico	9. Well No. No. 10
4. Location of Well UNIT LETTER "G" 1980' FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 34 TOWNSHIP 7-3 RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Chaveron - San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4399' DF	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well spudded October 9, 1965. Set 11 joints (355') of new 8-5/8" OD 24# 8-R S5 J-55 R-2 RT&C casing at 370' and cemented with 250 sacks by the Pump & Plug Process. Cement circulated to surface. Plug down at 11:15 P.M. October 9, 1965. W.O.C. 24 hours. Pressured up to 1000# for 30 minutes and casing tested OK. Drilled out cement plug and pressured up to 1000# for 30 minutes and casing shut off tested OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(ORIGINAL) **H. E. Asb**

SIGNED _____ TITLE **Dist. Supt.** DATE **October 22, 1965**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: