Form 9-331a		CUPY TO O. C. C.	
		m Approved.	No. 42-R358.4.
(Feb. 1951)	JUL 1 1963	MIT IN TRIPLICATE)	Cruses
	J. L. GORDON UN	VITED STATES OFFICE OCC	
	ACTING DISTBICT ENGINEE	ENT OF THE INTERIOR	
•	S GEOI	LOGICAL SURVEY 2 M 10 12	
	•	1953 JUL 2 M 10 12	
R3LE			1 196:
SUN	DRY NOTICES	AND REPORTS ON WELLS	JL 1 196:
			OLOGICAL SU
NOTICE OF INTENTION TO	0 DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<del>s, new mex</del> il
	O CHANGE PLANS		
	O TEST WATER SHUT-OFF		
NOTICE OF INTENTION TO	O RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
	D SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
	O PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO	O ABANDON WELL		
	· · · · · · · · · · · · · · · · · · ·		
	(INDICATE ABOVE BY CHECK MAI	RK NATURE OF REPORT, NOTICE, OR OTHER DATA)	
		1.3	
W Radamat W		July 1,	, 19 <b>63</b>
I. M. Federal F		and the second s	
ell No. 15	is located <b>1980</b> ft. from	m $\begin{cases} \mathbf{X} \\ \mathbf{S} \end{cases}$ line and <b>660</b> ft. from $\begin{cases} \mathbf{Y} \\ \mathbf{W} \end{cases}$ line of s	ec. <b>21</b>
NW/SW Sec 21	<b>8</b> 65	3LE NM PM	
(1/ Sec. and Sec. No.)	(1#P.)	(Range) (Meridian)	
Milnesand San		Maria Maria	
(Field)	(County		
		y or Subdivision) Will furnish (State or Territory)	
	derrick floor above sea le	y or Subdivision) Will furnish (State or Territory)	
	derrick floor above sea le	evel is ft.	
ne elevation of the	derrick floor above sea le DETA	vor Subdivision) Will furnish (Strigger Territory) evel isft.	
ne elevation of the	derrick floor above sea le DETA	evel is ft.	g jobs, cement-
ne elevation of the	derrick floor above sea le DETA depths to objective sands; show si ing points, and all	y or Subdivision) Will furnish (State or Territory) evel isft. AILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work)	
ne elevation of the ate names of and expected Set 8 5/8# 24#	derrick floor above sea le DETA depths to objective sands; show si ing points, and all	will furnish (State or Territory) evel isft. AILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work)	
ne elevation of the ate names of and expected Set 8 5/8* 24# psi for 30 min.	derrick floor above sea le DETA d depths to objective sands; show ai ing points, and all J55 Cag at 350' and Drill to T.D. 460	y or Subdivision) Will furnish (Stateor Territory) evel is ft. AILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) i circulate coment. Test csg to 100 00'.	
ne elevation of the ate names of and expected Set 8 5/8* 24# psi for 30 min, Set 42 9.5# J59	derrick floor above sea le DETA d depths to objective sands; show ai ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c	will furnish (State or Territory) evel isft. AILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work)	
ne elevation of the ate names of and expected Set 8 5/8* 24# psi for 30 min, Set 42 9.5# J59	derrick floor above sea le DETA d depths to objective sands; show ai ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c	y or Subdivision) Will furnish (Stateor Territory) evel is ft. AILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) i circulate coment. Test csg to 100 00'.	
ne elevation of the ate names of and expected Set 8 5/8* 24# psi for 30 min. Set 42 9.5# J59 psi for 30 min. Perf San Andres	derrick floor above sea le DETA d depths to objective sands; show ai ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c	y or Subdivision) Will furnish States evel is ft. AILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) I circulate cement. Test csg to 100 00'. cement w/200 sx. Test csg to 1500#	
ne elevation of the ate names of and expected Set 8 5/8* 24# psi for 30 min. Set 12 9.5# J55 psi for 30 min. Perf San Andrea ref. oil and sa	derrick floor above sea le DETA d depths to objective sands; show si ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c s and acidize w/2000 and in 4 stages w/b	y or Subdivision) Will furnish States evel is ft. ALS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) I circulate coment. Test csg to 100 0'. rement w/200 sx. Test csg to 1500# gal BDA. Sand Frac w/20,000 gal valls.	
ne elevation of the ate names of and expected Set 8 5/8* 24# psi for 30 min. Set 12 9.5# J55 psi for 30 min. Perf San Andrea ref. oil and sa	derrick floor above sea le DETA d depths to objective sands; show ai ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c	y or Subdivision) Will furnish States evel is ft. ALS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) I circulate coment. Test csg to 100 0'. rement w/200 sx. Test csg to 1500# gal BDA. Sand Frac w/20,000 gal valls.	
ne elevation of the ate names of and expected Set 8 5/8" 24# psi for 30 min. Set 12 9.5# J55 psi for 30 min. Perf San Andrea ref. oil and sa	derrick floor above sea le DETA d depths to objective sands; show si ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c s and acidize w/2000 and in 4 stages w/b	y or Subdivision) Will furnish States evel is ft. ALS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) I circulate coment. Test csg to 100 0'. rement w/200 sx. Test csg to 1500# gal BDA. Sand Frac w/20,000 gal valls.	
ne elevation of the ate names of and expected Set 8 5/8* 21# psi for 30 min. Set 12 9.5# J59 psi for 30 min. Perf San Andrea ref. oil and sa Run tog and put	derrick floor above sea le DETA d depths to objective sands; show ai ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c 5 Cag at 4600 and c s and acidize w/2000 and in 4 stages w/b t well on production	y or Subdivision) Will furnish Liter evel is ft. AILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) I circulate coment. Test cag to 100 00'. rement w/200 sx. Test cag to 1500# gal BDA. Sand Frac w/20,000 gal alls. on.	00
ne elevation of the ate names of and expected Set 8 5/8* 21# psi for 30 min. Set 12 9.5# J59 psi for 30 min. Perf San Andrea ref. oil and sa Run tog and put	derrick floor above sea le DETA d depths to objective sands; show si ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c 5 Cag at 4600 and c s and acidize w/2000 and in 4 stages w/b t well on production	y or Subdivision) Will furnish States evel is ft. ALS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) I circulate coment. Test csg to 100 0'. rement w/200 sx. Test csg to 1500# gal BDA. Sand Frac w/20,000 gal valls.	00
ne elevation of the ate names of and expected Set 8 5/8* 21# psi for 30 min. Set 12 9.5# J59 psi for 30 min. Perf San Andrea ref. oil and sa Run tog and put	derrick floor above sea le DETA d depths to objective sands; show si ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c 5 Cag at 4600 and c s and acidize w/2000 and in 4 stages w/b t well on production	y or Subdivision) Will furnish Liter evel is ft. AILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) I circulate coment. Test cag to 100 00'. rement w/200 sx. Test cag to 1500# gal BDA. Sand Frac w/20,000 gal alls. on.	00
ne elevation of the ate names of and expected Set 8 5/8* 24# psi for 30 min. Set 42 9.5# J59 psi for 30 min. Perf San Andrea ref. oil and sa Run tbg and put understand that this pla mpanySunray	derrick floor above sea le DETA depths to objective sands; show ai ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c 5 Cag at 4600 and c 5 and acidize w/2000 and in 4 stages w/b 5 well on production an of work must receive approval in DX 011 Co.	y or Subdivision) Will furnish Side of Perritory) evel is ft. ALS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) i circulate cement. Test csg to 100 o'. rement w/200 sx. Test csg to 1500# gal BDA. Sand Frac v/20,000 gal salls. on.	<b>20</b>
ne elevation of the ate names of and expected Set 8 5/8* 21# psi for 30 min. Set 12 9.5# J59 psi for 30 min. Perf San Andrea ref. oil and sa Run thg and put	derrick floor above sea le DETA depths to objective sands; show ai ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c 5 Cag at 4600 and c 5 and acidize w/2000 and in 4 stages w/b 5 well on production an of work must receive approval in DX 011 Co.	y or Subdivision) Will furnish Side of Perritory) evel is ft. ALS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) i circulate cement. Test csg to 100 o'. rement w/200 sx. Test csg to 1500# gal BDA. Sand Frac v/20,000 gal salls. on.	<b>20</b>
ne elevation of the ate names of and expected Set 8 5/8" 21# psi for 30 min. Set 12 9.5# J59 psi for 30 min. Perf San Andrea ref. oil and sa Run tog and put understand that this pla mpanySunray	derrick floor above sea le DETA d depths to objective sands; show si ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c 5 Cag at 4600 and c 8 and acidize w/2000 and in 4 stages w/b 5 well on production an of work must receive approval in r DX 011 Co.	y or Subdivision) Will furnish Side of Perritory) evel is ft. ALS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) i circulate cement. Test csg to 100 o'. rement w/200 sx. Test csg to 1500# gal BDA. Sand Frac w/20,000 gal valls. on. writing by the Geological Survey before operations may be con V. R. Mayable	<b>20</b>
he elevation of the ate names of and expected Set 8 5/8* 24# psi for 30 min. Set 12 9.5# J55 psi for 30 min. Perf San Andrea ref. oil and sa Run tog and put i understand that this pla mpanySunray dressP.0. Bo	derrick floor above sea le DETA d depths to objective sands; show si ing points, and all J55 Cag at 350' and Drill to T.D. 460 5 Cag at 4600 and c 5 Cag at 4600 and c 8 and acidize w/2000 and in 4 stages w/b 5 well on production an of work must receive approval in m DX 011 Co.	y or Subdivision) Will furnish Side of Perritory) evel is ft. ALS OF WORK izes, weights, and lengths of proposed casings; indicate mudding other important proposed work) i circulate cement. Test csg to 100 o'. rement w/200 sx. Test csg to 1500# gal BDA. Sand Frac v/20,000 gal salls. on.	<b>20</b>

GPO 914974

NEW MEXICO OIL CONSE WELL LOCATION AND ACR									FOR C-128 Revised S/1/57	
	SEI	INSTRUCTION			ORM ON	THE RE	AP Solf	FICE DCC		
perator				ECTION A			44	Vell Na		
	RAY DX OI	L CO.			N. M. FEDERAL			M 10: 1 15		
ait Letter	Section	Township		Range		County				
teal Footage Lo	21 cation of Vell	<b>I</b>	85	34	£.		ROOSEVE	L.T		
1980	feat from the	SOUTH	line and	660	feet	from the	WEST	line		
And Level Eler		Formation Andres	1	Pool Milnesand	San A	ndres	1	edicated Acr	rage:	
4283.9		Allui es		Milliesand				40	Acres	
WINGI IES		is "no," have the second secon	'yes," Type of	f Consolidation ad their respec		sts below:				
		SECTI	ON P						••••••••••••••••••••••••••••••••••••••	
		, T		<u>·</u>	ويدبنه والمتالك		C	ERTIFICATI	DN	
							in SECTION plate to the belief.	A above is the Mayabb	rse and com- owledge and	
		EG. PRAF	NGINEER &	LAND CHINE LUN	•	11	Company	t Enginee DX Oil Co 1963		
- <b>649</b>	3		JOHN W.				shown on the plotted from surveys mad supervision,	ify that the w plat in SECT field actes of by me ar un- and that the i o the best of i	FION B was actual ler my lame is true	
							Date Surveye	4 627-196	3	
							agiste red F	refensional E Surveyor, JC	agiaeer	