## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any stodifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention		Notice of Intention to	Notice of Intention			
to Change Plans		Temporarily Abandon Well	to Drill Deeper			
NOTICZ OF INTENTION		NOTICE OF INTENTION	Notice of Intention			
TO PLUG WELL		TO PLUG BACK	to Set Liner			
Notice of Intention to Squeeze			Notice of Intention to Shoot (Nitro)			
Notice of Intention to Gun Perforate		Notice of Intention (Other)	Notice of Intention (Other)			

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

TEXACO Inc. P. O. Box 728 - Hobbs, New Mexico January 2, 1964. (Date) (Place)

HOBBS OFFICE O.C.C.

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the								
TEXACO Inc. W	. L. Rogers				Well No.	1	in	В
NW 14 NE	(Company or Operator) 1/4 of Sec. 25	т. <sup>8</sup> -S	. <b>1</b> ение в 34-Е					(Unit) Pool
(40-acre Bubdivision) Roosevelt	Country		,					

## FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

We propose to do the following remedial work on subject well:

- Set cast iron cement retainer at 4710', perforations at 4720' to 4726'. 1.
- Establish approximately 1800 PSI injection pressure on casing by injecting lease 2. crude down casing-Tubing annulus, mixing formaseal in crude if necessary.
- Squeeze perforations at 4720' and 4726' with 25 sx latex cement. 3.
- Swab and recover formaseal and lease crude. 4.
- Set hookwall packer and acidize casing perforations between 4670' and 4691' with 5. 1600 gallons LSTNE 15% acid in 4 equal stages with 400 gallons per stage using ball sealers.
- 6. Swab well, test, return well to production.

J	TEXACO Inc.
Approved, 19	By Company or Operator
	H. D. Raymond Position Assistant District Superintendent
Approved 7 OIL CONSERVATION COMMISSION	Send Communications regarding well to:
By At	H. D. Raymond
Tible	Address P. O. Box 728 - Hobbs, New Mexico