

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Union Oil Company of California	8. Farm or Lease Name F. M. Tucker "3"
3. Address of Operator P. O. Box 671 - Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>7 South</u> RANGE <u>33 East</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) Est. 4379' GR.	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Re-entered old well June 30, 1977. Ran 8-5/8" x 10-3/4" x 3.86' Casing Bowl on 28 jts. & 1 piece (1,137.84') of 8-5/8" OD 24# K-55 New Casing set at 1,151' with 3.25' of 10-3/4" slipped down over top of 9-5/8" at 1,147.75'. Run drill pipe open ended to 2,068'. Spot Plug No. 1 2,068' to 1,900' with 100 sx cement. Spot Plug No. 2 from 1,600' to 1,450' with 50 sx cement. Pull and lay down 8-5/8" OD Casing. Spot Plug No. 3 from 1,159' to 1,030' with 75 sx cement. Spot Plug No. 4 from 405' to 258', in and out of bottom of 11-3/4" OD Casing at 360', with 100 sx cement. Place Plug No. 5 from 45' to surface with 25 sx cement. Weld steel plate on surface casing, install pipe marker, and plug and abandon in accordance with New Mexico O.C.C. rules and regulations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J.R. Hughes</u>	TITLE <u>District Drilling Supt.</u>	DATE <u>July 11, 1977</u>
APPROVED BY <u>Dist. 1, Supv.</u>	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY:

CEL 14177  
CEL COMPTON IN COMB.  
HOBBS, N. M.