

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. LC-062178
7. Lease Name or Unit Agreement Name Milnesand Unit
8. Well No. 92
9. Pool name or Wildcat Milnesand (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WIW	
2. Name of Operator Breck Operating Corp.	
3. Address of Operator P.O. Box 911, Breckenridge, TX 76424	
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>6</u> Township <u>8-S</u> Range <u>35-E</u> NMPM <u>Roosevelt</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4248' (GR)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Completed Operations

6/20/91: MIRU Ice Well Service. Rel pkr & POOH w/ 146 jts PC tbg & pkr. Set 4-1/2" CIBP on WL @ 4550'. RIH w/ tbg to 4550'. Load hole w/ 9.5# mud. Pmp 5 sx cmt on top of CIBP. POOH w/ tbg. RU to pull csg. Det csg free @ ±400'. SDON.

6/21/91: Shoot csg @ 404'. POOH w/ 13 jts 4-1/2" csg. RIH w/ tbg to 448'. Pmp 65 sx cmt. POOH w/ tbg. WOC 2 hrs. Tag TOC w/ WL @ 168'. RIH w/ 1 jt tbg. Pmp 15 sx cmt to surf. Cut off csg 3' below GR & weld on plate. RDMO.

6/25/91: Const dry-hole marker. Clean up loc.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kevin G. Duncan TITLE Petroleum Engineer DATE 7-3-91
TYPE OR PRINT NAME Kevin G. Duncan TELEPHONE NO. (817) 559-3355

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE July 21 1991
CONDITIONS OF APPROVAL, IF ANY: