

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

HUBBS OFFICE 16-962529-A

DEC 8 10 54 AM '66

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR FRANKLIN, ASTON & FAIR, INC.	9. WELL NO. Mark Federal
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface P. O. Box 1090, Roswell, New Mexico 660' FSL & 660' FWL Sec. 26-7S-35E	10. FIELD AND POOL, OR WILDCAT Todd Upper San Andres Todd Lower San Andres
14. PERMIT NO.	11. TOWN, RANGE, AND SECTION Sec. 26, T. 7 S., R. 35 E., N.M.P.M.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4188' DF	12. COUNTY OR PARISH Roosevelt
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☒
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In compliance with New Mexico Oil & Gas Conservation Commission Order R-3153 and upon approval of State Form C-107 already filed, we plan to dual complete this well. The well will be killed with water and tubing and packer pulled. The 5 1/2" casing will be perforated at selected intervals from 4111' to 4197' in the Todd Upper San Andres or "A Zone". Tubing will be rerun with a Guilberson KVL-30 packer and movable bridge plug which will be set at 4200' where the Anhydrite separates the Todd Upper Zone from Todd Lower San Andres "B Zone". The upper zone perms will be acidized through tubing. The bridge plug will then be pulled and the tubing and packer rerun with the packer set at 4200'. The Todd Upper San Andres will be produced through the annulus and the Todd Lower San Andres produced through the tubing.

18. I hereby certify that the foregoing is true and correct

SIGNED Grant M. Smith

TITLE

APPROVED

DATE November 29, 1966

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 30 1966
A. H. GRIFFIN
DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below cement plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and any well site conditioned for final inspection looking to approval of the abandonment.