

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K-1369

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name Hobbs "T"
3. Address of Operator PO Box 723, Hobbs, New Mexico 88240	9. Well No. 9
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>7S</u> RANGE <u>33E</u> N.M.P.M.	10. Field and Pool, or Wildcat Chaveroo San Andres
11. Elevation (Show whether DF, RT, GR, etc.) 4413' DF	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU 11/23/87. Pull rods and tubing.
- 2) GIH with 4 1/2" RBP and packer. Tag tight spot at 3515'. Pull out of tight spot.
- 3) Set packer at 3060'. Test backside to 500 psi. POH.
- 4) GIH with 4 1/2" CIBP. Set at 3055'. Circulate hole with inhibited water. Test to 350#, 12 minutes.
- 5) Well TR-0 effective 11/24/87.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

397-3571

SIGNED Paul Kautz TITLE Hobbs Area Superintendent DATE 12/11/87
Orig. Signed by
Paul Kautz
Geologist
APPROVED BY _____ TITLE _____ DATE JAN 1 1988
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 06 '88

O. E. D.
ARTESIA, OHIO

RECEIVED

JAN 17 1988

RECEIVED