

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JAN 7 1 32 PM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8946	
7. Unit Agreement Name	
8. Farm or Lease Name Atlantic State	
9. Well No. 1	
10. Field and Pool, or Wildcat Undesignated	
12. County Roosevelt	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole
2. Name of Operator W. G. Smith, Jr.
3. Address of Operator c/o Ernest A. Hanson, P. O. Box 1515, Roswell, New Mexico
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 7-S RANGE 35-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4234' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4 1/2" csg. set @ 4559'. Perfs. @ 4380-4537'. PBTD @ 4559'. TX @ 2230'.

The captioned well was P. & A. on Dec. 1, 1965, in the following manner:

1. A 25 sx. cmt. plug was set @ 4239-4559' across all perfs.
2. The 4 1/2" csg. was shot-off @ 2950' & the csg. recovered.
3. The hole was displaced with heavy mud.
4. A 25 sx. cmt. plug was set across the shot-off stub of 4 1/2" csg. @ 2907-3110'.
5. A 25 sx. cmt. plug was set @ the Top of Salt (2230') from 2187-2273'.
6. A 25 sx. cmt. plug was set @ the 8-5/8" csg. shoe (247') from 206-290'.
7. A 10 sx. cmt. plug was set @ the surface from 0-33' and a regulation dry hole marker erected.
8. The location was then cleaned up and made ready for inspection by the NMOCC.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Henry F. Schmitt</i></u>	TITLE <u>Geologist</u>	DATE <u>12/8/65</u>
APPROVED BY <u><i>Leslie A. Clement</i></u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		