

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)

COPY TO O. G. S.

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0108997-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Coquina Oil Corporation	8. FARM OR LEASE NAME Farrell Federal
3. ADDRESS OF OPERATOR P. O. Drawer 2960, Midland, TX 79701	9. WELL NO. 15
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FEL, Sec 28	10. FIELD AND POOL, OR WILDCAT Chaveron San Andres
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T-7-S, R-33-F
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4432'	12. COUNTY OR PARISH Roosevelt
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

Temporary Abandon

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Coquina Oil Corporation purchased this well from Mr. Weldon Guest on November 11, 1975. At the time of the purchase the well was uneconomical to produce, therefore, we have carried it as shut-in. The reasons Coquina has not plugged this well are that: currently, we are in the process of studying the possibility of a secondary recovery program, secondly, we may possibly return it to producing status, depending upon the price of oil in the future.

This approval of temporary
abandonment expires **DEC 1 1976**

18. I hereby certify that the foregoing is true and correct

SIGNED C. Alan BumpTITLE Engineering Asst.DATE 12-30-75

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

