NO. OF COPIES RECEIVED						Form C-103		
DISTRIBUTION						Supersedes Old		
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION					C-102 and C-103 Effective 1-1-65		
FILE	TEN MEXICO	J.E. CO.1.	ERTATION CO	mm(1331014		Effective 1-1-0	13	
U.S.G.S.						5a. Indicate Type	of Lease	
LAND OFFICE						State X	Fee	
						5. State Oil & Gas		
OPERATOR								
			·			NM10130, NM3	3934 - K2/34	
SUNDRY (DO NOT USE THIS FORM FOR PROPUSE "APPLICATION")	ONTICES AND REPORTED TO DEEPER ON FOR PERMIT - " (FORM C-1)	RTS ON	WELLS BACK TO A DIFFERE TH PROPOSALS.)	NT RESERVOIR.				
I. OIL V GAS T						7. Unit Agreement	Name	
WELL X WELL WELL	OTHER-					State 32 U	lñit	
2. Name of Operator						8. Farm or Lease	Name	
Champlin Petroleum Comp	any							
3. Address of Operator			· · · · · · · · · · · · · · · · · · ·			9. Well No.		
300 Wilco Building Midland, TX 79701						8		
4. Location of Well						10. Field and Pool, or Wildcat		
UNIT LETTER K 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM						Chaveron (San Andres)		
UNIT LETTER	FEET FROM THE	30 d Ci1	LINE AND	1300 F	ET FROM	77777777	7777777	
Mant	20	7	c	22 E				
THE West LINE, SECTION	t JZ township		O RANGE	33-E	NMPM.			
mmmmm	15. Elevation (Sho	111 111 kast	DE RT CP			12, County	444444	
		w wnetner	Dr, KI, GK, etc	•)		-		
ŽIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	4443 DF					Roosevelt	<u> </u>	
Check A	ppropriate Box To Inc	dicate N	ature of Noti	ce, Report	or Oth	er Data		
NOTICE OF IN			1	=		REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABA	NDON X	REMEDIAL WORK			ALTERIA	IG CASING	
TEMPORARILY ABANDON		لما	COMMENCE DRIL		ᅥ		;=	
7	CHANGE PLANS	. [7]	ĺ		-	PLUG AN	D ABANDONMENT	
PULL OR ALTER CASING	CHARGE PLANS	, L	CASING TEST AN	D CEMENT JOB			_	
			OTHER					
OTHER		—— [
17. Describe Proposed or Completed Ope	erations (Clearly state all pe	rtinent det	rils, and give per	tinent dates, in	ncluding e	stimated date of st	arting any propose	
work) SEE RULE 1103.					Ŭ			
	4							
Well uneconomical to pr	oduce.							
Proposed plugging proce	dure.							
						•		
Set CIBP @ 4100' and ca	p w/50' cement.	Locate	4-1/2" ca	sing free	e poin	t. (Should b	oe at	
approximately $1400' \pm 1.00$ at top of $4-1/2''$ casing	Cut off 4-1/2"	casing	at free p	oint. Se	et 100	' cement plu	ig centered	
at top of $4-1/2$ " casing	stub. Set 100'	pluq a	cross surf	ace casir	ng show	e 0 369'. S	Set 10 sx	
plug in top of surface	pipe with marker	instal	led. Flui	d betweer	plug	s to be 10#/	dal mud.	
Prug III oop or surrace	L. La a		··-·		, 3		J	
San Andres Perfs 4214'-	.44281							
Juli Aliurus (Ciris Triff -								
		1930	·					
	Commence of the second							
	門の気傷の気	CNELL	n de la Santa Turbis de de la Santa					
	10 E A		The Carlo	Control Control				
10 I beachy contifu that the information	housis tous and received	45-1	£ 1 1					
18. I hereby certify that the information a	pove is true and complete to	the best of	my knowledge a	nd belief.				
110			trict Supe					
SIGNED M. W. Timm			<u>lling & Pr</u>			DATE 7/14	1/83	
ORIGINAL SIGNED &	Y JERRY SEXTON							
APPROVED BY DISTRICT (1.	PART OF THE	TLE				DATE	י איז	
CONDITIONS OF APPROVAL IS ANY						DATEUUL	- 6861 - 0 -	

CONDITIONS OF APPROVAL, IF ANY: