SANTA FE U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROFOSALS TO DRILL OR TO DEFFER OR PLUS BACK TO A DIFFERENT RESERVOIR. OIL SAND OF OPERATOR OUT WELL A WELL OTHER. 2. Name of Operator JOSEPH 1. O'NEILL, JR. 3. Address of Operator 410 WEST ONIO, MIDLAND, TEXAS 4. Location of Well UNIT LETTER D 660 PEET PROM THE MORTH LINE AND 660 PEET PROM THE WEST LINE, SECTION 16 TOWNSHIP 8-S RANGE 36-E NAMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4120 NB Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUS AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB A COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB A COTHER	12. County ROOSEVELT
SUNDRY NOTICES AND REPORTS ON WELLS (OO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SACK TO A DIFFERENT RESERVOIR. 1. OKEL	State A Fee 5. State Oil & Gas Lease No. E-8875 7. Unit Agreement Name 8. Farm or Lease Name STATE **L** 9. Well No. 3 10. Field and Pool, or Wildcat SOUTH PRAIRIE (SAN ANDRE) 12. County ROOSEVELT her Data T REPORT OF:
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 1. OIL	5, State Oil & Gas Lease No. E-8875 7, Unit Agreement Name 8, Farm or Lease Name STATE *L* 9, Well No. 3 10, Field and Pool, or Wildcat SOUTH PRAIRIE (SAN ANDR 12. County ROOSEVELT her Data T REPORT OF:
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 1. OIL	7. Unit Agreement Name 8. Form or Lease Name STATE "L" 9. Well No. 3 10. Field and Pool, or Wildcat SOUTH PRAIRIE (SAM ANOR 12. County ROOSEVELT her Data T REPORT OF:
1. OIL SAS GAS WELL OTHER- 2. Name of Operator JOSEPH 1. O'NEILL, JR. 3. Address of Operator 410 WEST ONIS, MIDLAND, TEXAS 4. Location of Well UNIT LETTER D 660 FEET FROM THE MORTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 16 TOWNSHIP 8-S RANGE 36-E NAMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4120 RB 16. Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PROPOSALS. FOR THE NAME OF NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK CHANGE PLANS CASING TEST AND CEMENT JOB B.	7. Unit Agreement Name 8. Farm or Lease Name STATE "L" 9. Well No. 3 10. Field and Pool, or Wildcat SOUTH PRAIRIE (SAN AMPR 12. County ROOSEVELT her Data T REPORT OF:
1. OIL WELL OTHER. 2. Name of Operator JOSEPH I. O'NEILL, JR. 3. Address of Operator 410 WEST ONIO, MIDLAND, TEXAS 4. Location of Well UNIT LETTER D . 660 FEET FROM THE NORTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 16 TOWNSHIP 8-S RANGE 36-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4120 KB 16. Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OFNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB B.	8. Form or Lease Name STATE "L" 9. Well No. 3 10. Field and Pool, or Wildcat SOUTH PRAIRIE (SAN ANOR 12. County ROOSEVELT her Data T REPORT OF:
JOSEPH 1. O'NEILL, JR. 3. Address of Operator 410 WEST ONIO, MIDLAND, TEXAS 4. Location of Well UNIT LETTER B 660 FEET FROM THE MORTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 16 TOWNSHIP 8-S RANGE 36-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4120 NB 16. Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB X	9, Well No. 3 10. Field and Pool, or Wildcat SOUTH PRAIRIE (SAN ANDR 12. County ROOSEVELT her Data T REPORT OF:
4. Location of Well UNIT LETTER D 660 PEET PROM THE NORTH LINE AND 660 PEET PROM THE WEST LINE, SECTION 16 TOWNSHIP 8-S RANGE 36-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4120 RB Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JQB X	3 10. Field and Pool, or Wildcat South Prairie (San Andre 12. County ROOSEVELT her Data T REPORT OF:
UNIT LETTER D , 660 PEET PROM THE NORTH LINE AND 660 PEET PROM THE WEST LINE, SECTION 16 TOWNSHIP 8-S RANGE 36-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4120 RB 16. Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JQB X	SOUTH PRAIRIE (SAN ANDR 12. County ROOSEVELT her Data T REPORT OF:
THE WEST LINE, SECTION 16 TOWNSHIP 8-S RANGE 36-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4120 RB 16. Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JQB X	12. County ROOSEVELT her Data T REPORT OF:
Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB	ROOSEVELT her Data T REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JQB	T REPORT OF:
OTHER	PLUG AND ABANDONMENT
OTHER	
SPUDDED 1:30 P.M. 2-8-66, 12 1/4" HOLE TD = 329' 8 5/3 312.96', CASING SET AT ROB = 323.96', CEMENTED W/210 SCHLORIDE = 247 CU. FT. CIRCULATED OUT APPROX 10 SX. WOC FOR 18 HRS. TESTED 1000 FOR 30 MIN. TESTED OK.	BX REGULAR + 25 CALC
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	