

| | | |
|-----------------|--|--|
| COPIES RECEIVED | | |
| TRIBUTION | | |
| FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

X

| | |
|--------------------------------|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|---|--|---|
| 1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> <u>Gene Milford Pipe & Supply Co.</u> | | 7. Unit Agreement Name <u>Bradley</u> |
| 2. Name of Operator <u>Box 427 Tatum, NM 88267</u> | | 8. Farm or Lease Name <u>2</u> |
| 3. Address of Operator <u>0 660 South 1980</u> | | 9. Well No. <u>Chaveroo San Andres</u> |
| 4. Location of Well UNIT <u>East</u> <u>24</u> FEET FROM THE <u>7-3</u> LINE AND <u>33-E</u> FEET FROM THE _____ LINE, SECTION _____ TOWNSHIP _____ RANGE _____ NMPM. | | 10. Field and Pool, or Wildcat |
| 15. Elevation (Show whether DF, RT, GR, etc.) | | 12. County |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | |
|--|---|
| REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE Well Plugged & Abandoned as follows:

3-13-74

Set CIBF @ 3990'
Dumped 35' Cement from 3990 to 3955'
Shot 4 1/2" Csg. @ 1091 & 981'
Recovered csg. 981'
Spotted 40 sk cmt plug @ 981' to 361'
Spotted 50 sk cmt plug @ 495' to 375'
Spotted 10 sk cmt plug @ 10' to surface

Installed dry hole marker

Note: All plugs set with and hole circulated w/ brine salt gelled mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

owner

4-17-74

SIGNED

Gene Milford

TITLE

DATE

APPROVED BY

John W. Runyan

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: