NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION	HOBBS OFFICE O. C. C.	Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	MAR 16 1 30 PH '66	
U.S.G.S.	MARIO 1 30 III UU	5a. Indicate Type of Lease
LAND OFFICE		State Fee.
OPERATOR		5. State Oil & Gas Lease No.
		R - 1369
SUNDRY (DO NOT USE THIS FORM FOR PROPUSE "APPLICATION.") 1.	Y NOTICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL	OTHER-	•
2. Name of Operator Shelly Ctl Compa	K T	8. Farm or Lease Name Rebbs "T" 7.8. \$2
3. Address of Operator Box 730 - Hobbe,	New Mexico	9. Well No.
4. Location of Well	-	10. Field and Pool, or Wildcat
UNIT LETTER	50 FEET FROM THE SOUTH LINE AND 1980 FEET	FROM Chaveroo San Andres
THE LINE SECTION	35 TOWNSHIP 7-8 RANGE 33-8	
LINE, SECTION	RANGE N	мем.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County Recovals
16. Check A	ppropriate Box To Indicate Nature of Notice, Report or	r Other Data
NOTICE OF IN		JENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	1
TEMPORARILY ABANDON		ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
TOSE ON ACTEN GROUNG	OTHER	,
OTHER	OTHER	
4-1/2" OD 10.5# & consut by the pur Temperature surve the surface. W.O	th of 4500° on March 11, 1966. Set 141 jts R 38 J-55 RT & C casing at 4500°. Commted up & plug process. Fing down at 12:00 Midniq indicated commt outside of 4-1/2° 99 cast 0.C. 24 hrs. Pressured up to 600f for 30 minot drill out coment plug. P.B.T.B. 4458°.	with 350 sacks of ght March 12, 1966. ing at 3187' from
(SRIGINAL) H. E.		t Manuels 14 1044
SIGNED	TITLE District Superintendent	L DATE March 16, 1966

CONDITIONS OF APPROVAL, IF ANY: