N. M. OIL CONS. COMMISSION P. O. BOX 1980 Form approved. Budget Bureau No. 42-R1424. DEPARTMENT OF THE INTERIOR verse side Form 9-331 (May 1963) 5. LEASE DESIGNATION AND SERIAL NO. NM-042253 GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL Y GAS WELL OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR Fed. 🕏 Dalport Oil Corporation 9. WELL NO. 3. ADDRESS OF OPERATOR 3471 Inter First One, Dallas, TX 75202 10. FIELD AND POOL, OR LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Chaveroo -Dan andre 11. SEC., T., R., M., OR BLK. AND 660' FNL & 660FEL Letter "A" 26-T7S-R33E 12. COUNTY OR PARISH 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. Roosevelt NM Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT ABANDONMENT* SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE CHANGE PLANS REPAIR WELL (Nore: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) * T.D. 4400', PBTD 4367', Perfs. 4119' - 4259' 8 5/8" Casing set @ 363 Circulated. $4\frac{1}{2}$ " Casing set @ 4397 w/300 SX PROCHEDURE: 12/7/87 Set CIBP @ 4000' w/35' Cement on plug, Ran tubing to 3900' 12/8/87 Circulate $4\frac{1}{2}$ " Casing w/ salt gel mud, pulled tubing to 3150' spot 15 SX cement plug 3150' to 3000' in $4\frac{1}{2}$ " casing, shot $4\frac{1}{2}$ ' casing @ 380' spot, 45SX cement plug across 8 5/8" shoe & $4\frac{1}{2}$ " casing stub, Tagged cement plug @ 235' spot 10SX cement plug @ surface & install dry hole marker NOTE: Will notify USGS when location cleaned and ready for final inspection. 18. I hereby certify that the foregoing is true and correct DATE 12/17/87 Agent TITLE (This space for Federal or State office (ise) Approved as to plugging of the well bore. DAPPROVED PETER W. CHESTER APPROVED BY Liability under bond is retained until CONDITIONS OF APPROVAL, IF ANY: surface restoration is completed. JAN 2 1 1988 *See Instructions on Reverse Side

2

DUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA JAM OF TORRO