

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>2. Name of Operator <b>Morris R. Antweil</b></p>		<p>5. State Oil &amp; Gas Lease No. <b>K-4840</b></p>
<p>3. Address of Operator <b>Box 2010, Hobbs, New Mexico</b></p>		<p>7. Unit Agreement Name <b>*****</b></p>
<p>4. Location of Well UNIT LETTER <b>L</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>8</b> TOWNSHIP <b>7S</b> RANGE <b>34E</b> NMPM.</p>		<p>8. Farm or Lease Name <b>Capitan</b></p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) <b>KB 4336'</b></p>		<p>9. Well No. <b>1</b></p>
<p>12. County <b>Roosevelt</b></p>		<p>10. Field and Pool, or Wildcat <b>Wildcat</b></p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4290'. Cemented 4-1/2" 9.5# new csg. @ 4289' w/325 sx. WOC 24 hrs. Tested to 1000 psi. for 30 minutes. No decline in pressure. Top cmt. 3200'. Perforated 4030', 4052', 4072', 4132', 4142', 4149', 4155', 4162' & 4172'. Treat w/1500 gals. MCA. SF w/30,000 gals. crude oil containing 30,000# sand. Production tested 5 BOPD + 22 Bbls. Water. Plan to plug and abandon, 9-28-66, as follows: (Verbal approval by J. D. Ramey)  
25 sx. cement plug on bottom across perforations.  
Cut and pull 4-1/2" casing from 3200'.  
25 sx. cement plug across 4-1/2" casing stub.  
25 sx. cement plug across top salt (approx. 1650')  
25 sx. cement plug in base of 8-5/8" surface casing @ 403'.  
10 sx. cement plug @ surface w/marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Burt Helton* TITLE Agent DATE 9-28-66  
APPROVED BY *J. D. Ramey* TITLE Dist. Super DATE 9-30-66  
CONDITIONS OF APPROVAL, IF ANY: