

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY HOLE		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Fred Pool Operating Company		5. State Oil & Gas Lease No.
3. Address of Operator Post Office Box 1393, Roswell, New Mexico 88201		7. Unit Agreement Name
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 7S RANGE 32E NMPM.		8. Farm or Lease Name Sams
		9. Well No. #1
		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4470.28 GR		12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-28-82

Plug No. 1

- 1) Ran tubing open-ended to 4307'. Pumped 20 sx Class "C", neat, (330' of fill = 151' above top perf).

Plug No. 2

- 2) Pulled tubing up to 1805', pumped 15 sx Class "C", 4% CaCl. Pulled tubing up & out of cmt., shut down for the day.

12-29-82

- 1) Tagged Plug No. 2 @ 1901'. (NOTE: Cement plug did set but had dropped approx. 300', therefore an additional 15 sx of cmt was placed on top of it.)
- 2) Pulled 1 jt. of tubing, pumped 15 sx @ 1869'.
- 3) Pulled all tubing out of hole.
- 4) Placed 10 sx cement at surface.
- 5) Installed dry hole marker.

OCD will be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Fred T. Pool TITLE Petroleum Engineer DATE 12/30/82

APPROVED BY Ronald M. Cantrell TITLE OIL & GAS INSPECTOR DATE OCT 4 - 1985

CONDITIONS OF APPROVAL, IF ANY: