

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION
MAY 28 11 19 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
3. Address of Operator <u>Sun Oil Company</u>		9. Well No. <u>4</u>
4. Location of Well <u>P. O. Box 2792, Odessa, Texas</u>		10. Field and Pool, or Wildcat
UNIT LETTER <u>L</u> , <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1979.5</u> FEET FROM		<u>Chaveroo SA</u>
THE <u>South</u> LINE, SECTION <u>20</u> TOWNSHIP <u>7 S</u> RANGE <u>33 E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.) <u>4429' cr.</u>		12. County <u>Roosevelt</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	
		OTHER <u>and logging</u>	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-14-66 Lane Wells ran Gamma Ray Density w/caliper, 100 to 4342, Focus Log 2200 to 4336. Minifocus 2200 to 4343. 5-15-55 ran 118 jts. 4 1/2" OD 9.5# 8R and 7 jts. 4 1/2" OD 10.5 8R casing, seated at 4340. Cemented w/225 sks incor w/4% gel w/.5% DS-30. Twenty three Kluck scratchers 16' apart 4013 to 4332. Eleven Kluck positive centralizers 1 jt. apart from 4000 to 4335. WOC 24 hours. Tested 4 1/2" casing 2000# 30 min. o.k. Tom Hansen ran temperature survey, TOC 3520.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Foreman DATE 5-18-66

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

6711