UNITED STATES

SUBMIT IN TRIPLICATE*
(Other instructions on re-

Form approved, Budget Bureau No. 42-R1424.

	DEPARTMENT OF THE IN		5. LEASE DESIGNATION AND SERIAL NO. NM- 0558287
	NDRY NOTICES AND REPORT is form for proposals to drill or to deepen or Use "APPLICATION FOR PERMIT—" for	- · · · · · · · · · · · · · · · · · · ·	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS			7. UNIT AGREEMENT NAME
WELL WELL 2. NAME OF OPERATOR	OTHER	TO A Corporate	S. FARM OR LEASE NAME
	CTION COMPANY.	The Control of the Co	MORGAN D FEDERAL
BOX 367, A	NDREWS, TEXAS 79714	MAR 15 18/19	9. WELL NO.
4. LOCATION OF WELL See also space 17 be At surface	(Report location clearly and in accordance wielow.)	1058S NEW STEEL	CHAUEROS- SAN AND
660' FSL -	1980 FEL Sec. 13 (Uni	t O, SW/4 SE/4)	13-7-33 NMPM
14. PERMIT NO.	15. ELEVATIONS (Show who 43 25		12. COUNTY OB PARISH 13. STATE
16.	Check Appropriate Box To India	ate Nature of Notice, Report, or	Other Data
	NOTICE OF INTENTION TO:	SUBSEC	QUENT REPORT OF:
		-1 1	
TEST WATER SHUT FRACTURE TREAT SHOOT OR ACIPYZE REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		REPAIRING WELL ALTERING CASING ABANDONMENT* Is of multiple completion on Well pletion Report and Log form.)
FRACTURE TREAT SHOOT OR ACIPYZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED proposed work, nent to this work. W. W	MULTIPLE COMPLETE ABANDON* CHANGE PLANS OR COMPLETED OPERATIONS (Clearly state all p If well is directionally drilled, give subsurfate) PAA 3-6-76.	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report result Completion or Recom- ertinent details, and give pertinent dates ce locations and measured and true verti-	ALTERING CASING ABANDONMENT* Its of multiple completion on Well pletion Report and Log form.) s, including estimated date of starting any cal depths for all markers and zones perti-
FRACTURE TREAT SHOOT OR ACIPYZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED Proposed work, nent to this work. Will Can Can Spal 8	MULTIPLE COMPLETE ABANDON* CHANGE PLANS OR COMPLETED OPERATIONS (Clearly state all p if well is directionally drilled, give subsurfa P+A 3-6-76. Push wor BP & Det (S Sx lement 3035-26)	shooting on acidizing (Other) (Note: Report result Completion or Reconsections and measured and true vertice locations and measured and frue vertice) 3 954. Capped 6	ALTERING CASING ABANDONMENT* Its of multiple completion on Well pletion Report and Log form.) s, including estimated date of starting any

Spot 35 & 435'300'; 10 5x @ surface w/ P+A marker. Heavy mud between all plugs. Final cleanup shall be made in accordance W/ new mercie dept of Dame + Fish's requirements.

18. I hereby certify that the threeging is true and co	TITLE ADMINISTRATIVE ASSISTANT	DATE 3-12-76
(This space for Federal or Style office use)	ADPRO	44
APPROVED BY	TITLE	1971 DATTO/
O+A-USGS-H) - Div	JAN 25	***OWN
1-501P 1-8RY	*See Instructions on Reverse Side ARTHUR R	" CMS."