

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM 050477 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CARD-FEDERAL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Chaveroo-San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

27-7-33

12. COUNTY OR PARISH

Roosevelt

13. STATE

N. M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

GEROR OIL LIMITED 1962

3. ADDRESS OF OPERATOR

1846 East Broadway, Tucson, Arizona

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980/N & W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4407 KB

4396 GR (corrected)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-18-66 Spud well 3:50 PM. Run 8 jts. 8 5/8" - 20# casing @ 372' and cemented with 200 sacks with 2% calcium Chloride. Plug Down 9 PM

8-26-66 Lost Circulation 4224

8-29-66 TD 4500' - Run logs

8-30-66 TD 4500' - Run 141 jts. 5 1/2" - 14# casing @ 4440' with 350 sacks Incon Permox cement. PBD 4431.

9-1-66 Perforate 11 - 1/2" hole 1 SPI @ 4156, 68, 93, 4219, 34, 49, 69, 75, 80, 92, and 4303. Treat perforations with 2500 gals. NE acid.

9-2-66 Recover acid water and load oil. Flow test well for 8 hours. Flow 88 bbls. New Oil in test on 20/64" choke.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE 9-6-66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

SEP 7 1966

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.