

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM 050477 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CARD-FEDERAL

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Cheveree-San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

27 - 7 S - #36

12. COUNTY OR PARISH

ROOSEVELT

13. STATE

N MEX

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

GEROR OIL LIMITED 1962

3. ADDRESS OF OPERATOR

1846 East Broadway, Tucson, Arizona

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980/N 660/W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4399 GR

4410 KB

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-19-66 Spud well - Ran 8 jts 20# 8-5/8" casing @ 360' w 200 ex Incon Cont 2% Cacl
20 Tested casing 30 minutes with 800# - No leak
29 T O 4600' dolomite
30 Logging well - Ran 143 jts. 14# 5 1/2" casing @ 4600' w 400 ex Incon
Foamix cont w 2% gel.
11- 1-66 Perforate 11 - 1/2" holes @ 4176,85, 4230,37,52,60,67,76,81,87,95
Treat perforations w 2500 gals. regular NE acid. Packer @ 4140'.
Swab load oil and test.
2 Swab new oil to tanks.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

11-2-66

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 8 1966

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER

eral and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid content not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

907-851