

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
ROOSEVELT, NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-0139989

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Todd Lower San Andres
Unit

8. FARM OR LEASE NAME

Todd Lower San Andres
Unit Section 30

9. WELL NO.

20-3

10. FIELD AND POOL, OR WILDCAT

Todd Lower San Andres Assoc.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 30, T-7S, R-36E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

MURPHY OPERATING CORPORATION

3. ADDRESS OF OPERATOR

P. O. Box 2648, Roswell, New Mexico 88202-2648

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit Ltr. C, 1871.3' FWL & 660' FNL, Sec. 30, T-7S, R-36E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☒

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9/22/87 RU PU, unhang well. Unseat pump. Pull rods. Picked up ont jt. tubing, tagged bottom and talleyed out of hole. 4316.57' TD SLM. Run back in hole with tubing to 4294.87. Pumped 500 gallons 15% NEFE Acid with xylene. RD acid crew. Ran back in hole with pump and rods. Respaced well and hung well back on. RD PU.



I hereby certify that the foregoing is true and correct

SIGNED

Matt Murphy

TITLE Production Agent

DATE 10/22/87

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
JAN 13 1988
BUREAU OF LAND MANAGEMENT
ROOSEVELT RESOURCE AREA

*See Instructions on Reverse Side