

ESTES ENGINEERING CO.

Consulting Petroleum Engineers

208 PETROLEUM LIFE BLDG.

MIDLAND, TEXAS 79701

W.C.C.

APR 23 1 23 PM '67

APRIL 24, 1967

ESTES ENGINEERING COMPANY

MARKHAM-STATE NO. 1

TEST SUMMARY

CORE NO. 1

4666'-4716'. RECOVERED 47-1/2' OF SLIGHTLY
POROUS OIL STAINED DOLOMITE, BLEEDING GAS FROM
RANDOM FRACTURES.

DST NO. 1

4650'-4716'. OPEN 5 MINUTES SI 1 HOUR.
OPEN 2 HOURS, SI 1 HOUR. OPENED WITH WEAK BLOW, INCREAS-
ING TO FAIR BLOW REMAINING STEADY THROUGHOUT TEST.
RECOVERED 2100' OF GAS IN DRILL PIPE AND 100' OF
GAS CUT MUD.

PRESSURES:	1 HS	2682
	1SIP	842
	IF	99
	FF	111
	FSIP	270
	F HS	2667

ESTES ENGINEERING CO.

Engineering, Planning, Design
and Construction Services
Midland, Texas 79701

7/11/87

10/11/87

10/11/87

10/11/87

10/11/87

10/11/87

10/11/87

10/11/87