

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-3995	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Monument Energy Corporation		8. Farm or Lease Name Anderson State	
3. Address of Operator Box 1476, Lovington, New Mexico 88260		9. Well No. 6	
4. Location of Well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM THE <u>west</u> LINE, SECTION <u>36</u> TOWNSHIP <u>7S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat Chaveroo San Andres	
15. Elevation (Show whether DF, RT, GR, etc.) 4448.7 GR		12. County Roosevelt	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Pulled rods and tubing. Set CIBp @ 3975 and dumped 5 sacks cement on top of plug. Circulated hole with 10# mud. Shot casing @ 1086 and recovered same. Went in hole with tubing and spotted 35 sack plug @ casing stub. Pulled tubing to 350' and set 35 sack plug @ bottom of surface. Set P & A marker with 10 sacks cement @ surface.

Used Permian Basin Casing Pullers to plug well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C. H. July</u>	TITLE <u>Production Foreman</u>	DATE <u>3/1/77</u>
MAR 16 1977		
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		

ENCLOSURE

MAY 14 1977
OIL CONSERVATION COMM.
HOBBS, N. M.