| r | | | |
|---|------------------------------|-------------------------------|---|
| COPIES RECEIVED | | | Form C-103 Supersedes Old |
| TRIBUTION | | | C-102 and C-103 |
| FE | NEW MEXICO OIL CONSE | ERVATION COMMISSION | Effective 1-1-65 |
| FILE | | | |
| U.S.G.S. | | | Sa. Indicate Type of Lease State X Fee |
| LAND OFFICE | | | |
| OPERATOR | | | 5. State Oil & Gas Lease No. |
| | | | $\frac{B-10130}{1}$ |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) | | | |
| 1. | | | 7. Unit Agreement Name |
| OIL GAS WELL | OTHER- | | |
| 2. Name of Operator | | | 8. Farm or Lease Name |
| Cene Milford dba Milford Pipe & Supply | | | Hondo State |
| 3. Address of Operator | | | 9. Well No. |
| Box 427 Tatum, N.M. | | | 2 |
| 4. Location of Well | | | 10. Field and Pool, or Wildcat |
| UNIT LETTER <u>E 660</u> FEET FROM THE West LINE AND <u>1980</u> FEET FROM | | | Chaveroo |
| | | | |
| THE North LINE, SECTION | | | |
| THE CINE, SECTION | | | |
| 15. Elevation (Show whether DF, RT, GR, etc.) | | | 12. County |
| AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII | | | Roosevelt |
| ^{16.} Check A | ppropriate Box To Indicate N | ature of Notice, Report or Ot | her Data |
| | | | T REPORT OF: |
| | | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON | | COMMENCE DRILLING OPNS. | PLUG AND ABANDONMENT |
| F=1 | CHANGE PLANS | CASING TEST AND CEMENT JOB | |
| PULL OR ALTER CASING | | | |
| | [] | - men | |
| OTHER | | | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

August 1, 1974

Well Plugged and Abandoned as follows:

Set Cast Iron Bridge Plug @ 4100' & dupmet 35' cmt on plug Shot and recovered 42" Casing from 3302' Spotted @ 45 sk cmt plug from 3302' to 3145' Spotted @ 45 Sk cmt plug from 400' to 280 Spotted @ 45 sk cmt plug @ surface & installed Dry H^{*}le Marker

Hole was circulated with and all plugs set with salt water brine gel

| 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | |
|--|-----------|--------------|--|--|
| SIGNED Lene milford | | Aug 20, 1974 | | |
| APPROVED BY APPROVAL, IF ANY: | Geologiss | EB2219/7 | | |