

COPIES RECEIVED	
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-10130
7. Unit Agreement Name
8. Farm or Lease Name
9. Well No. Hondo State
10. Field and Pool, or Wildcat Chaveroo San And
12. County Roosevelt

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Gene Milford dba Milford Pipe & Supply
3. Address of Operator Box 427 Tatum, NM 88267
4. Location of Well UNIT LETTER C 1980 FEET FROM THE West LINE AND 660 FEET FROM THE North NE, SECTION 31 TOWNSHIP 7-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4446.1 G. I.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandon as follows:

Aug. 3 1974

Set Cast Iron Bridge plug @ 4100' & dumped 35' cement on plug  
Shot casing @ 2998, & 1516' & recovered  
Spotted a 45 sk cement plug from 1516' to 1359'  
Spotted a 45 sk cement plug from 425' to 310'  
in and out of 8-5/8" surface csg.  
Spotted 10 sk cement plug at surface & installed dry hole marker

Hole was circulated with and all plugs set with salt water brine gel

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Gene Milford</u>	TITLE <u>owner</u>	DATE <u>8-20-74</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>FEB 22 1975</u>
CONDITIONS OF APPROVAL, IF ANY:		