Form 3160-5 November 1983) Formerly 9-331)

UNITE STATES L 1 STATES DEPARTMENT OF THE INTER OF THE

norm approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.

BUREAU OF LAND MANAGEMEN HOBBS, NEW MEXICO 882	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	7. UNIT AGREEMENT NAME
OIL GAS WELL OTHER	TODD LOWER SAN ANDRES UNIT
2. NAME OF OPERATOR	8. FARM OR LEASE NAME Todd Lower San Andres Unit
MURPHY OPERATING CORPORATION 3. ADDRESS OF OPERATOR	Sec. 30
P. O. Drawer 2648, Roswell, New Mexico 88201	16
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT
See also spince 17 below.) At surface 660 FSL & 660' FEL, Sec. 30, T-7S, R-36E Roosevelt County, New Mexico	Todd Lower San Andres Assoc. 11. BEC., T., B., M., OR BLK. AND SURVEY OR AREA
	Sec. 30, T-7S, R-36E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
4129.1' GR	Roosevelt New Mexico
16. Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data
•••	DENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT WILLTIPLE COMPLETE FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING
FRACTURE TREAT SHOOT OR ACIDIZE MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING X	<u>-</u>]
SHOOL OR REIDING	nt & perforate X
(Other) (Norz: Report results	of multiple completion on Well letion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work. If well is directionally drilled, give subsurface locations and measured and true vertice	including estimated date of starting any
POH. RU & ran sand pump, cleaned out 7' fill. RU & ran Gamma II attached) 4276' - 3900'. TOH w/log. TIH w/perf gun and pdia. 1 JSPF, 50 shots, 4223'-4273'. TOH w/perf gun. TIH acidized w/500 gals. Xylene, 2000 gals. 20% NEFE, 500# salw/1000 gals. 2% KCl water @ avg. press. 2500 psi, max. pre 6 BPM, ISIP @ 1100 psi @ 2 min. vac. Unseat pkr. & TOH w/8rd EVE tbg 4273.72' (3' off btm.).	perforated as follows: .50 w/pkr. & set @ 4144', & lt block & overflushed ess. 2850 psi, & avg. rate /pkr. TIH w/135 jts. 2-3/8"
Nipple up WH & break dn. power swivel & load same. Tih w. 5/8" rods & 63 3/4" rods w/subs & polish rod w/8 liner. NOV 1	/gas lock valve, pump, 104' TOH & had good pump action.
18. I hereby certify that the foregoing is true and correct	
SIGNED Lois N. Brown TITLE Production Records Lois N. Brown PETER W. CHESTER	DATE Nov. 13, 1984
(This space for Federal or State office use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY: FEB 1 1985	DATE
BUREAU OF LAND MANAGEMENT *See Instruction ROB WIELDER STATE CE AREA	

OF MINED

FEB -4 1985

HOSS CHACE