

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR AMOCO PRODUCTION COMPANY	8. FARM OR LEASE NAME PETERSON A Federal
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240	9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT TODD LOWER SAN ANTONIO
14. PERMIT NO. 1980 FNL x 560 FWL Sec 29 (Unit E SW 1/4 NW 1/4)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 29-7-36
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4152 R. D. B.	12. COUNTY OR PARISH ROOSEVELT
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was TA on 3-7-68. Propose to P.A. as follows:

Spot 254. cement plug from PBD 4297 to cover perys 4240-86.

Shoot and pull 4 1/2" CG from Free Point (see 2400')

255x Plug - @ 2100' if CG pulled from below 2100'.

2 in + put of 4 1/2" stick if pulled above 2100'.

255x plug in & out of 8 7/8" CSA 325.

10 SX @ surface w/ P.A. marker. All intervals mud filled.

Make final cleanup and restore ground to contour.

TD - 4324' 8 7/8" CSA 325 - circ

PBD - 4297' 4 1/2" CSA 4324' - 300 SX.

PERFS - 4240-86

18. I hereby certify that the foregoing is true and correct

SIGNED _____

TITLE AREA SUPERINTENDENT

DATE

MAR 9 1971

(This space for Federal or State office use)

APPROVED BY _____

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

MAR 10 1971

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

ON 4. USGS-11
1- AC 31
1- SUSP
1- R.R.Y