

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instruction
reverse side)

TE
re

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0467935-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 30

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Chaveroo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 30, T-7-S, R-33-E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Southwestern Natural Gas, Inc.

3. ADDRESS OF OPERATOR

900 Bank of the Southwest - Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980 FNL & 660 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4429 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

6-29-68: Perforated at 4157', 66', 82', 88', 4224', 40', 60', 80', 4301',
07, 46, 53, 58, and 66'.

Acidized w/ 1000 gls acid

Fracture treated w/ 40,000 gls ref oil plus 3# sand/gal in 3 stages.

6-30-68: SI

7-1-68: Prep to flow back load.

7-2-68: Running rods and tubing. Prep to put on pump.

18. I hereby certify that the foregoing is true and correct

SIGNED Jan R. Cannon TITLE Office Manager

DATE 7-3-68

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED

DATE _____

JUL

5 1968

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER